

CCU / FE720009689 / Aes3



VEHICLE INSPECTION ESTIMATE

Address : 1 Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)

REG NO : 201828067M

Insurance Company: MS FIRST CAPITAL INSURANCE LIMITED
(MOTOR CLAIMS DEPARTMENT)

Address: NO 36, ROBINSON ROAD, #16-01
CITY HOUSE, S(068877)

Asher.

Telephone: 65073848 Fax: 65073849 Email motorclaims@msfirstcapital.com.sg

Make/ Model : HYUNDAI ACCENT

Date: 05.09.2020

Chassis No : KMHCU41BTKU481321

Vehicle No: SMU983Z

Date/Time of Accide 31.08.2020/ 2020

DATE OF REG: 29.07.2020

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	REAR END PANEL <i>Regr</i>	1	\$ 608.70		\$ 608.70 +
2	REAR END PANEL TOP GARNISH <i>Regr</i>	1	\$ 192.50		\$ 192.50 +
3	BOOTLID <i>Regr</i>	1	\$ 1,198.60		\$ 1,198.60 +
4	BOOTLID INNER TRIM <i>Free</i>	1	\$ 285.10		\$ 285.10 +
5	BOOTLID HINGE <i>Free</i>	2	\$ 145.80		\$ 291.60 +
6	BOOTLID OUTER STOPPER <i>Free</i>	2	\$ 40.50		\$ 81.00 +
7	BOOTLID INNER STOPPER <i>Free</i>	2	\$ 38.50		\$ 77.00 +
8	BOOTLID INNER TRIM <i>Free</i>	1	\$ 105.60		\$ 105.60 +
9	BOOTLID LOGO <i>Regr</i>	1	\$ 85.60		\$ 85.60 ✓
10	BOOTLID "ACCENT" EMBEM <i>Regr</i>	1	\$ 79.50		\$ 79.50 ✓
11	BOOTLID WEATHERSTRIP <i>Free</i>	1	\$ 192.60		\$ 192.60 +
12	BOOTLID INNER LOCK <i>Free</i>	1	\$ 185.90		\$ 185.90 +
13	BOOTLID OUTER GARNISH <i>Free</i>	1	\$ 236.70		\$ 236.70 +
14	BOOTLID NUMBER PLATE LAMP <i>Free</i>	2	\$ 80.90		\$ 161.80 +
15	REAR BUMPER <i>Regr</i>	1	\$ 679.80		\$ 679.80 483 ✓
16	REAR BUMPER REFLECTORS <i>Regr</i>	1	\$ 154.60		\$ 154.60 +
17	REAR BUMPER SIDE RETAINERS <i>Regr</i>	2	\$ 75.90		\$ 151.80 +
18	REAR BUMPER REINFORCEMENT <i>Regr</i>	1	\$ 698.90	390.80	\$ 698.90 ✓
19	REAR REINFORCEMENT BRACKETS <i>Regr</i>	2	\$ 69.70		\$ 139.40 +
20	TAILAMP <i>Regr</i>	2	\$ 495.20	395	\$ 990.40 495.20 ✓
21	TAILAMP INNER SEALER <i>Regr</i>	2	\$ 38.50		\$ 77.00 38.50 ✓
Total List Price Cost					\$ 6,674.10
PARTS DISCOUNT 20%					\$ 5,339.28

1472.4

1177.92

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00 ✓
2	REAR NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00	\$ 50.00 +
3	BOOTLID INNER TRIM CLIPS <i>part</i>	1 SET	\$ 30.00	\$ 30.00 +
4	END PANEL TOP GARNISH CLIPS <i>part</i>	1 SET	\$ 30.00	\$ 30.00 +
5	REVERSE SENSORS <i>brand</i>	1 SET	\$ 250.00	\$ 250.00 -20
6	END PANEL TOP GARNISH CLIPS <i>part</i>	1 SET	\$ 30.00	\$ 30.00 +
7	END PANEL SEALANTS <i>part</i>	2	\$ 80.00	\$ 80.00 +
8	TAILAMPS CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00 -20
Total Special Nett Items				\$ 560.00

250

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 1,200.00
<i>300</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,200.00
<i>400</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00 +
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 150.00 -50
LABOUR TO APPLY SEALANT TO THE AFFECTED AREAS	\$ 150.00 +
TO REMOVE/ REFIT WIRING CHECKS ON TAILAMPS	\$ 120.00 -30
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 150.00 -50
TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	\$ 150.00 +
Total Others Cost	\$ 920.00
GRAND TOTAL	\$ 9,219.28

810

*Admin G
r/s 10/09/20
03 Dyp*

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allan@casgarage.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tolal: 2237.92

r/s: 1750 ✓