

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 17 Sep 2020

Preliminary Advice

Insured Vehicle No : FBN4171R

TP Vehicle No : SJM6135T

Make : TOYOTA VIOS

Date of Inspection : 15/09/2020

Inspection At : Xinya Auto Services Pte Ltd (HQ)
Blk 1002, #01-75, Bukit Merah Lane 3
Singapore 159719

Accident Date : 28/08/2020

Assignment Date : 10/09/2020

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,269.93
Revised Amount	:S\$	1,400.66
Check Items (Estimated)	:S\$	216.01
Total	:S\$	1,616.67

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.