

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 10-Sep-20

Address : DEREK SCOTT KHOO YAM SEONG
BLK 105 BUKIT PURMEI ROAD
#12-09
SINGAPORE 090105

Reference : TP 1254/09/20
Vehicle No : SMJ 7529P
Make/Model : VW SCIROCCO
Insurance Co. : NTUC

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE : QUOTATION TO SMJ 7529P FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		<u>QTY</u>		<u>AMT \$</u>
1)	FRONT BUMPER	1	\$	1,677.31 <i>RY</i>
2)	FRONT BUMPER RETAINER	1	\$	60.77 <i>X</i>
3)	FENDER RH	1	\$	688.74 <i>bx</i>
4)	FENDER COWLING RH	1	\$	288.95 <i>de</i>
5)	CLIPS	10	\$	71.10 <i>X</i>

LIST PRICE TOTAL	\$	2,786.87
LESS DISCOUNT 10%	\$	278.69
LIST PRICE TOTAL AFTER LESS	\$	2,508.18

NETT PRICE TOTAL \$0.00

TOTAL PARTS COST \$2,508.18

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER & FENDER RH AND TO PANEL & ALIGN.	\$	600.00 <i>300</i> (3 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER & FENDER	\$	600.00 <i>400</i> (3 PANEL)
3)	TO FOCUS HEADLAMP CHECK AND RECTIFY WIRING.	\$	80.00 <i>30</i>

LABOUR TOTAL \$ 1,280.00

TOTAL ESTIMATED REPAIR COST \$ 3,788.18

Tanph 97445747
up 15/9/2010
3 days C/S Repair after repair.
Tanph C. K. K. K.