



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SMT1062E

Date of Accident : 09 September 2020

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Muhammad Azri Bin Azman

Date : 10 September 2020

Estimate To Repair SJP8604C - Hyundai Getz 1.4 5DRA

Chassis No : KMHBU51DR9U908060

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper R	\$ 311.90 X
02	10 ps	front bumper clip @ \$4.50 NY	\$ 45.00 X
03	1 pc	o/s front bumper side retainer 11	\$ 45.00 X
04	1 pc	o/s front fender Body 20	\$ 372.00 /
05	1 pc	o/s front fender inner cowling 70.11	\$ 253.00 /
06	6 ps	o/s front fender inner cowling clip @ \$4.50 MC	\$ 27.00 /
07	1 pc	o/s front fender mudflap De/ueq 6	\$ 65.00 /
08	1 pc	o/s front door 20/But	\$ 843.00 /
09	1 pc	o/s front door pad 910nd	\$ 85.00 /
10	1 pc	o/s side mirror assy 11	\$ 480.00 X
11	1 pc	o/s headlamp 300/11C	\$ 380.00 X
12	1 pc	o/s front wheel bearing	\$ 89.00 ?
13	1 pc	o/s front lower arm	\$ 223.60 ?
14	1 pc	o/s front steering rack tie rock 11	\$ 185.00 X
15	1 pc	steering rack and pinion assy 11	\$ 1,529.00 X
16	1 pc	o/s front knuckle arm	\$ 280.00 ?
Less 20 %			\$ 5,213.50
			\$ 1,042.70
			\$ 4,170.80
<u>SPECIAL NETT ITEMS</u>			
17	1 pc	o/s front sport rim 20/But	\$ 350.00 300 S.N
			\$ 350.00
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of tyre, rim and on wheel balancing.	\$ 11 80.00 X
02		To check steering geometry and computer wheel alignment.	\$ 120.00 100
03		To transfer of door fittings and perform water seepage test.	\$ 80.00 50
04		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 200.00 120
05		To perform water seepage test, windnoise and test-drive.	\$ 1 180.00 X
06		To check electrical lighting concerned.	\$ 80.00 20
07		To provide administrative works, application and reseal off-peak car licence plate.	\$ 50.00 /
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00 400



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SMT1062E
Date of Accident : 09 September 2020

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Muhammad Azri Bin Azman

Date : 10 September 2020

Estimate To Repair SJP8604C - Hyundai Getz1.4 5DRA
Chassis No : KMHBU51DR9U908060

S/No	Quantity	Description	Amount
09		<u>LABOUR & MISC. CHARGES</u>	
		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 2,590.00
		Total	\$ 7,110.80

600

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S.N-300
L-1340