

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : **Toyota Vios**
 Registraion No : **SGT 8574 U**
 Chassis No: **MR053HY9305147039**
 Year of Manufacturing: **2009**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper ?	\$ 854.10	\$ 854.10
2	1	RHS Front Bumper Retainer ?	\$ 68.50	\$ 68.50
3	1	LHS Front Bumper Retainer ?	\$ 68.50	\$ 68.50
4	1	RHS Front Bumper Bracket ?	\$ 58.90	\$ 58.90
5	1	LHS Front Bumper Bracket ?	\$ 58.90	\$ 58.90
6	1	Front Bumper Reinforcement ?	\$ 458.70	\$ 458.70
7	1	Front Bumper Grille / AR	\$ 398.80	\$ 398.80
8	1	Front Bumper Lower Grille / BR	\$ 361.50	\$ 361.50
9	1	Front Bumper Grille Logo ?	\$ 59.70	\$ 59.70
10	1	RHS Headlight ?	\$ 470.50	\$ 470.50
11	1	LHS Headlight ?	\$ 470.50	\$ 470.50
12	1	Front Support Panel BT photo	\$ 554.70	\$ 554.70
13	1	Front Support Panel Top Garnish ?	\$ 123.50	\$ 123.50
				\$ 4,006.80
				-25% \$ 1,001.70
Total for spare parts				\$ 3,005.10

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett

1	10	Front Bumper Clip / <i>MD</i>	\$	5.00	\$	50.00
2	10	Front Support Panel Top Garnish Clip ↑	\$	5.00	\$	50.00

No. plate ✓ BT

Total for SP	<u>\$</u>	100.00
Sub-Total for Parts :	<u>\$</u>	3,105.10

S/No	Qty	Items	Unit Price	Amount
------	-----	-------	------------	--------

1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	500.00 <i>400</i>
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	500.00 <i>400</i>
3		Apply rust proofing on the adjacent panels	\$	50.00 X
4		To supply under coating / putty on parts replaced	\$	50.00 X
5		To perform water seepage test after repair	\$	80.00 X
6		To focus headlight	\$	80.00 <i>30</i>

TOTAL AMOUNT :	<u>\$</u>	1,260.00
OVERALL COST:	<u>\$</u>	4,365.10

*4 Days .
 Unpsum repair .
 After repair photos .
 Cam. Q: onf .
 11/9/2020 .*