

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : **Toyota Vios**
 Registraion No : **SGT 8574 U**
 Chassis No: **MR053HY9305147039**
 Year of Manufacturing: **2009**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper ✓ BR	\$ 854.10	\$ 854.10 399.6
2	1	RHS Front Bumper Retainer ✓ BR	\$ 68.50	\$ 68.50 63.4
3	1	LHS Front Bumper Retainer ✓ BR	\$ 68.50	\$ 68.50 63.4
4	1	RHS Front Bumper Bracket ✗ NN	\$ 58.90	\$ 58.90
5	1	LHS Front Bumper Bracket ✗ NN	\$ 58.90	\$ 58.90
6	1	Front Bumper Reinforcement ✓ BT	\$ 458.70	\$ 458.70 312.3
7	1	Front Bumper Grille / BR	\$ 398.80	\$ 398.80 285.2
8	1	Front Bumper Lower Grille / BR	\$ 361.50	\$ 361.50 69.6
9	1	Front Bumper Grille Logo ✓ DE	\$ 59.70	\$ 59.70 58.2
10	1	RHS Headlight ✓ BR	\$ 470.50	\$ 470.50 425
11	1	LHS Headlight ✓ BR	\$ 470.50	\$ 470.50 425
12	1	Front Support Panel ✗ photo	\$ Repair 554.70	\$ 554.70
13	1	Front Support Panel Top Garnish ✗	\$ NN 123.50	\$ 123.50
				<u>\$ 4,006.80</u> 2371
				-25% \$ 1,001.70
Total for spare parts				<u>\$ 3,005.10</u>

1778.55

RADIATOR TOP GARNISH ✓ DE 269.7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Special Nett

1	10	Front Bumper Clip / <i>md</i>	\$	5.00	\$	50.00	20
2	10	Front Support Panel Top Garnish Clip X	\$NN	5.00	\$	50.00	
		<i>Na. plate</i> ✓ <i>BT</i> 40					
						Total for SP	\$ 100.00 60
						Sub-Total for Parts :	\$ 3,105.10

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	500.00 350 400
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	500.00 300 400
3		Apply rust proofing on the adjacent panels	\$	50.00 X
4		To supply under coating / putty on parts replaced	\$	50.00 X
5		To perform water seepage test after repair	\$	80.00 X
6		To focus headlight	\$	80.00 30
TOTAL AMOUNT :				\$ 1,260.00 680
OVERALL COST:				\$ 4,365.10

4 Days

2518.55

-20%: 2000

ump sum repair.

After repair photos.

Car. Q: onf.

11/9/2020