



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20009707/Apa3q2	
			Date: 15/12/2020	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7086X	Veh. Inspected	SKT 8765M
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D20003631MFSH	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	10/09/2020
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A6	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WAUZZZ4G6EN173540	Colour	WHITE
	Odometer	106221 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/09/2020	Inspection Date	10/09/2020
	Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 8765M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	DEFORMED	2,537.00	2,537.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	272.00	-
1	REAR BUMPER SPOILER (SN)	DEFORMED	343.00	342.50
1	REAR BUMPER SECURING STRIP (SN)	NOT NECESSARY	170.00	-
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	960.00	-
2	REAR BUMPER CARRIER SEAL -LH/RH (SN)	NOT NECESSARY	28.00	-
2	REAR BUMPER GUIDE SECTION -LH/RH (SN)	NOT NECESSARY	66.00	-
2	REAR BUMPER CONNECTING PIECE (SN)	NOT NECESSARY	25.00	-
2	REAR BUMPER GUIDE PROFILE -LH/RH UPPER (SN)	NOT NECESSARY	114.00	-
1	REAR BUMPER GUIDE SECTION -CENTRE (SN)	NOT NECESSARY	105.00	-
1	REAR BUMPER CARRIER COVER -RH (SN)	NOT NECESSARY	114.00	-
2	REAR PARKING AID SENSOR (SN) (NPA)	NN	-	-
1	BOOT LID CONTROL UNIT (SN)	NOT NECESSARY	399.00	-
1	EXHAUST TAIL PIPE TRIM (SN)	NOT NECESSARY	561.00	-
1	SUNDRIES (SN)	NOT NECESSARY	200.00	-
			5,894.00	2,879.50
	<u>LABOUR</u>			
	TO REMOVE & REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION .		360.00	360.00
	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS.		1,200.00	800.00
	TO RESPRAY REAR BUMPER .		1,000.00	800.00
	TO CARRY OUT DIAGNOSTIC CHECK .		192.00	192.00
			2,752.00	2,152.00
GRAND TOTAL			8,646.00	5,031.50
RECOMMENDED COST OF REPAIRS				5,031.50

Report Ref No. CC4/FCI20009707/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 8765M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 8765M

RE-INSPECTION

