

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : Ubi Road 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0645/2020/TT
DATE : 9-Sep-20
WIP : 48455

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

MS FIRST CAPITAL INSURANCE PTE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 0689877

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LI BAO SHUN
ADDRESS : 130 TANJONG RHU ROAD
#08-08
SINGAPORE 436918
TELEPHONE : HP +65 97659758
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : VA1/GA343948
VEHICLE NO : **SKT 8765 M**
MODEL CODE : AUDI A6 C7 2.0 TFSI MU 4G
MODEL YEAR : 26/5/2015
ENGINE NO : CDN 412656
CHASSIS NO : WAUZZZ4G6EN173540
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Sep-20
PLACE OF ACCIDENT : AYE TO KEPPEL ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE ~~SFZ 8200 Z~~ SKT 8765M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N	\$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS.	S/N	\$ 1,200.00	sw
3	TO RESPRAY REAR BUMPER	S/N	\$ 1,000.00	sw
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ 2,752.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ~~SFZ 8300 Z~~ SKT 8765M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>del</i>		\$	2,537.00	✓
2 REAR BUMPER FIXING PARTS <i>del</i>		\$	272.00	+
3 REAR BUMPER SPOILER <i>del</i>		\$	343.00	✓ 342.50
4 REAR BUMPER SECURING STRIP ? NN		\$	170.00	X
5 REAR BUMPER CARRIER ? NN		\$	960.00	X
6 REAR BUMPER CARRIER SEAL - LH/RH <i>del</i>	2	\$	28.00	+
7 REAR BUMPER GUIDE SECTION - LH/RH <i>del</i>	2	\$	66.00	+
8 REAR BUMPER CONNECTING PIECE <i>del</i>	2	\$	25.00	+
9 REAR BUMPER GUIDE PROFILE - LH/RH UPPER } <i>del</i>	2	\$	114.00	X
10 REAR BUMPER GUIDE SECTION - CENTRE } <i>del</i>		\$	105.00	+
11 REAR BUMPER CARRIER COVER - RH } <i>del</i>		\$	114.00	+
12 REAR PARKING AID SENSOR <i>del</i>	2		TBC	+
13 BOOT LID CONTROL UNIT } <i>del</i>		\$	399.00	✓
14 EXHAUST TAIL PIPE TRIM } <i>del</i>		\$	561.00	+
15 SUNDRIES ? NN		\$	200.00	X
TOTAL SPARE PARTS	:	\$	5,894.00	
TOTAL LABOUR CHARGES	:	\$	2,752.00	
GRAND TOTAL	:	\$	8,646.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME : Admin Ly
SURVEYED DATE : 10/09/2017
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT