

Hsiao Tong (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 25 November 2020 6:08 PM
To: Adrian Ling (LKKAuto); CS A Team; Admin A; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SKT8785M - TP FIRSTCAP - SURVEYED 10 SEP 20
Attachments: PA06452020 - SKT 8765 M- Audi A6 C7 2.0 TFSI MU 4G - REAR - TP (MS FIRST).xlsx;
WhatsApp Image 2020-09-23 at 4.20.02 PM.jpeg; WhatsApp Image 2020-09-23 at
4.19.50 PM.jpeg; WhatsApp Image 2020-09-23 at 4.19.56 PM.jpeg

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$5031.50 @ 3 days of repairs.

Your early closure is well appreciated.

Best regards - jb

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



WIP : 48445

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0645/2020/NS
Date : 9-Sep-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no : SHC 7086 X

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Hi Adrian

3 days - ok - jb - 25 Nov 20

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mr Li Baoshun
Address : 130 Tanjong Rhu Road
#08-08
Singapore 436918
Telephone : HP +65 97659758
Type of Claim : Third Party Claim
Policy No. : VA1/GA343948
Vehicle No : **SKT 8765 M**
Model Code : Audi A6 C7 2.0 TFSI MU 4G
Model / Year : 26/5/2015
Engine No : CDN 412656
Chassis No : WAUZZZ4G6EN173540
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Sep-20
Place of Accident : AYE To Keppel Road



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 8765 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S COMMENDATI
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	\$ 360.00 ✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	\$ 800.00 ✓
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00	\$ 800.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 2,752.00	\$ 2,152.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 8765 M

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,537.00	\$ 2,537.00
2	REAR BUMPER FIXING PARTS	\$ 272.00	
3	REAR BUMPER SPOILER	\$ 343.00	\$ 342.50
4	REAR BUMPER SECURING STRIP	\$ 170.00	
5	REAR BUMPER CARRIER	\$ 960.00	
6	REAR BUMPER CARRIER SEAL - LH / RH	2 \$ 28.00	
7	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 66.00	
8	REAR BUMPER CONNECTING PIECE	2 \$ 25.00	
9	REAR BUMPER GUIDE PROFILE - LH / RH UPPER	2 \$ 114.00	
10	REAR BUMPER GUIDE SECTION - CENTRE	\$ 105.00	
11	REAR BUMPER CARRIER COVER - RH	\$ 114.00	
12	REAR PARKING AID SENSOR	2 TBC	
13	BOOT LID CONTROL UNIT	\$ 399.00	
14	EXHAUST TAIL PIPE TRIM	\$ 561.00	
15	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS		: \$ 5,894.00	\$ 2,879.50
TOTAL LABOUR CHARGES		: \$ 2,752.00	\$ 2,152.00
GRAND TOTAL		: \$ 8,646.00	\$ 5,031.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant