



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104948

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 13/07/2021
Reference CC4/FCI20009709/Kgs3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLG 5786D

Insured Veh. SH 6929P

Claim No. D20003473MFSH

Policy No. D-20094922MFSH

Accident Date 17/07/2020

Inspection Date 09/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20009709/Kgs3q2	
			Date: 13/07/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6929P	Veh. Inspected	SLG 5786D
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20003473MFSH	Excess (\$)	0.00
	Assign From	CHRIS	Assign Date	09/09/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTDKB3FU703535341	Colour	METALLIC PEARL WHITE
	Odometer	223288 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	3 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	3 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	4 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/07/2020	Inspection Date	09/09/2020
	Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 5786D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP LH	CUT	2,531.60	2,531.60
1	FRONT BUMPER	BUCKLED / CRACKED	450.80	450.80
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER REINFORCEMENT -UPPER	TO REPAIR SEE LABOUR	711.50	-
1	FRONT BUMPER REINFORCEMENT -LOWER	TO REPAIR SEE LABOUR	245.30	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	107.20	-
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	107.20	107.20
1	FRONT BUMPER TOW COVER LH	SERVICEABLE	25.70	-
	LESS 25% DISCOUNT		-1,054.83	-782.40
			3,164.47	2,347.20
<u>LABOUR</u>				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA .(FRONT BUMPER).INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT -UPPER AND FRONT BUMPER REINFORCEMENT -LOWER .		400.00	200.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA .(FRONT BUMPER).		400.00	220.00
	TO CHECK WIRING .		50.00	20.00
			850.00	440.00
GRAND TOTAL			4,014.47	2,787.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CC4/FCI20009709/Kgs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 5786D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 5786D

RE-INSPECTION

