

First Capital a/a



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
Tel : 6484 1221 Fax : 6484 7829
385 Sin Ming Drive (Inside Vicom) Singapore 575718.
Tel : 6753 2112 Fax : 6451 0394
Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Repair Estimates

SLG 5786 D

| | | |
|-----------------------------------|-----------|-----------------|
| Parts (a) Cost / List Price Items | \$ | 4,219.30 |
| Plus/Less 25% | \$ | 1,054.83 |
| Total of Cost / List | \$ | 3,164.48 |
| (b) Nett Price Items | | |
| Less | | |
| Total of Nett Item | | |
| (c) Special Nett Items | | |
| Total Parts Cost | \$ | 3,164.48 |
| Labour | \$ | 850.00 |
| Total | \$ | 4,014.48 |

The above total will be subjected to 7% G.S.T.

Not Authorised
L1 Syg &
McLurey Ate Paim

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$

(e) Signature of surveyor

PC

Date: 9/9/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Spare Parts

Vehicle No. :

SLG 5786 D

Submit By :

SERENCE

Make & Model :

TOYOTA PRIUS

Year Manufacture :

5-Oct-16

Chassis No. :

JTDKB3FU703535341

Engine No. :

Cost / List

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|---|-----|------------|-------|-------------------------|
| 1 | Headlamp LH <i>Cur</i> | 1 | \$2,531.60 | | ✓ |
| 2 | Front bumper <i>Bul/10A</i> | 1 | \$450.80 | | ✓ |
| 3 | Front bumper clip <i>new</i> | 10 | \$40.00 | | ✓ |
| 4 | Front bumper reinforcement - upper <i>N</i> | 1 | \$711.50 | | X |
| 5 | Front bumper reinforcement - lower <i>N</i> | 1 | \$245.30 | | X |
| 6 | Front bumper side retainer RH <i>SL</i> | 1 | \$107.20 | | X |
| 7 | Front bumper side retainer LH <i>DI</i> | 1 | \$107.20 | | ✓ |
| 8 | Front bumper tow cover LH <i>SL</i> | 1 | \$25.70 | | X |
| 9 | | | | | |
| 10 | | | | | |
| 11 | | | | | |
| 12 | | | | | |
| 13 | | | | | |
| 14 | | | | | |
| 15 | | | | | |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
Tel : 6484 1221 Fax : 6484 7829
385 Sin Ming Drive (Inside Vicom) Singapore 575718,
Tel : 6753 2112 Fax : 6451 0394
Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

| | | | |
|----------------|---------------------|-----------------------|-------------------|
| Vehicle No. : | <u>SLG 5786 D</u> | Submit By : | <u>Carmen Lim</u> |
| Make & Model : | <u>TOYOTA PRIUS</u> | Year of Manufacture : | <u>42648</u> |

[illegible]

Scanned with CamScanner