



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2105982

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 24/08/2021
Reference CC4/EQI20009717/Des3q2
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 8814E
Insured Veh. PUBLIC LIABILITY
Claim No. DL20HO00056/CL
Policy No.
Accident Date 04/09/2020
Inspection Date 11/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CC4/EQI20009717/Des3q2 Date: 24/08/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SHC 8814E	
Policy No.		Coverage (\$)	0.00	
Claim No.	DL20HO00056/CL	Excess (\$)	0.00	
Assign From	Steve Lim	Assign Date	11/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203563984	Colour	BLUE	
Odometer	361366 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/09/2020	Inspection Date	11/09/2020	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8814E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	950.50	950.50
1	INSULATOR ,HOOD	NOT NECESSARY	398.10	-
10	INSULATOR CLIPS	NOT NECESSARY	36.80	-
1	BONNET CABLE	NOT NECESSARY	83.20	-
1	BONNET HINGE (RH)	TO REPAIR SEE LABOUR	87.70	-
1	BONNET HINGE (LH)	BENT	87.70	87.70
1	BONNET LOCK	BENT	132.60	132.60
1	CATCH ,HOOD AUXILIARY HOOK	BENT	8.60	8.60
1	RADIATOR GRILLE	BROKEN	438.00	438.00
1	RADIATOR GRILLE EMBLEM	DISLODGE / BROKEN	88.00	88.00
1	FRONT BUMPER COVE	TORN	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	BENT	696.40	696.40
1	FRONT BUMPER REINFORCEMENT ABSORBER	NOT NECESSARY	115.70	-
1	FRONT BUMPER LOWER REINFORCEMENT	NOT NECESSARY	364.20	-
1	FRONT BUMPER LOWER REINFORCEMENT BRACKET	NOT NECESSARY	330.00	-
2	FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) @\$320.70	NOT NECESSARY	641.40	-
1	FRONT SIDE MEMBER SIDE COVER	NOT NECESSARY	172.50	-
1	FRONT BUMPER SPONGE	TORN	78.80	78.80
1	FRONT BUMPER LOWER GRILLE	CRACKED / DEFORMED	148.60	148.60
1	LAMP ASSY ,FOG, RH	NOT NECESSARY	920.00	-
1	LAMP ASSY ,FOG, LH	MTG CRACKED	920.00	920.00
1	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE RETAINER (N/S)	BROKEN	77.00	77.00
1	FRONT LOWER PANEL	NOT NECESSARY	320.65	-
2	FRONT LOWER SIDE RAIL (LH/RH) @\$230.80	NOT NECESSARY	461.60	-
1	FRONT LOWER CROSSMEMBER	NOT NECESSARY	357.70	-
1	FRONT UNDER COVER	NOT NECESSARY	180.80	-
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	225.40	-

Report Ref No. CC4/EQI20009717/Des3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER ,FRONT BUMPER HOLE ,RH	NOT NECESSARY	28.38	-
1	COVER ,FRONT BUMPER HOLE ,LH	DISLODGE	28.38	28.38
1	ABSORBER ,FRONT BUMPER ,LOWER	NOT NECESSARY	127.70	-
1	UNIT ASSY ,HEADLAMP ,RH (LED)	MTG CRACKED	3,455.00	2,637.60
1	UNIT ASSY ,HEADLAMP ,LH (LED)	BROKEN	3,455.00	2,637.60
1	HEADLAMP ECU	NOT NECESSARY	682.60	-
1	HEAD LAMP PANEL (RH)	BENT	240.10	240.10
1	HEAD LAMP PANEL (LH)	BENT	240.10	240.10
1	TOP PANEL CENTRE	BENT	364.98	364.98
1	TOP PANEL SIDE	BENT	145.90	145.90
1	BRACE PANEL	BENT	75.20	75.20
1	RADIATOR ASSY	BENT / PUNCTURE	1,841.80	1,841.80
1	RADIATOR FAN GRILLE	NOT NECESSARY	632.40	-
1	GUIDE RADIATOR AIR NO.3	NOT NECESSARY	299.70	-
1	COOLANT	NOT NECESSARY	45.00	-
1	DEFLECTOR ,RADIATOR SIDE ,RH	NOT NECESSARY	83.50	-
1	DEFLECTOR ,RADIATOR SIDE ,LH	BROKEN	83.50	83.50
1	RADIATOR SPARE TANK HYBRID	NOT NECESSARY	225.80	-
1	RADIATOR BOTTOM MOUNTING	NOT NECESSARY	27.50	-
1	STAY ,RADIATOR SUPPORT ,RH	NOT NECESSARY	65.70	-
1	STAY ,RADIATOR SUPPORT ,LH	NOT NECESSARY	65.70	-
1	RADIATOR FAN BLADE (RH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN BLADE (LH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN MOTOR (RH)	NOT NECESSARY	543.70	-
1	RADIATOR FAN MOTOR (LH)	NOT NECESSARY	543.70	-
2	RADIATOR FAN COWLING (LH/RH)@\$451.30	NOT NECESSARY	902.60	-
1	RESERVE TANK ASSY ,RADIATOR W/O CAP	NOT NECESSARY	395.30	-
2	HORN (1 PC) @\$112.71	NOT NECESSARY	225.42	-
1	CONDENSER ASSY ,W/RECEIVER	BENT / PUNCTURE	1,336.60	1,336.60
1	FENDER SUB-ASSY,FRONT LH	BUCKLED	945.30	945.30
1	FRONT HOUSING ASSY	TO REPAIR SEE LABOUR	945.26	-
1	FRONT FENDER SHIELD	SERVICEABLE	198.50	-

Report Ref No. CC4/EQI20009717/Des3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER SHIELD CLIP	NOT NECESSARY	14.90	-
1	FRONT FENDER HYBRID EMBLEM ,LH	NECESSARY	86.50	86.50
1	BRACKET ,FRONT SIDE PANEL, LH	NOT NECESSARY	86.30	-
1	TRAY ,BATTERY	NOT NECESSARY	42.80	-
	LESS 20% DISCOUNT		-5,558.17	-
	LESS 25% DISCOUNT		-	-3,702.92
			22,232.70	11,108.74
	<u>NETT ITEMS</u>			
1	FRONT NO.PLATE GARNISH (N)	CUT	99.00	99.00
	LESS 25% DISCOUNT		-	-24.75
			99.00	74.25
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO.PLATE (SN) }	DISLODGE	25.00	45.00
1	FRONT NO.PLATE TRIM COVER (SN) }	DISLODGE	30.00	-
1	FRONT BUMPER LOGO (SN)	NOT NECESSARY	87.10	-
			142.10	45.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET HINGE (RH) AND FRONT HOUSING ASSY .		1,400.00	800.00
	SPRAY PAINTING CHARGE.		1,200.00	800.00
	WIRING CHARGE.		160.00	30.00
	TUFF KOTE.		140.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	RE-SET FRT ABS SYSTEM.	NOT NECESSARY	200.00	-
	REMOVE/REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			3,950.00	1,950.00
	GRAND TOTAL		26,423.80	13,177.99

Report Ref No. CC4/EQI20009717/Des3q2



RECOMMENDED COST OF REPAIRS			13,177.99
-----------------------------	--	--	-----------

Report Ref No. CC4/EQI20009717/Des3q2

A handwritten signature in black ink, appearing to be 'Ang Bryan Tani'.

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8814E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8814E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8814E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

