



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



WIP : 47821

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0631/2020/NS
Date : 4-Sep-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

4 days - ok - Jy - 16 Nov 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lee Wai Meng (Li Weiming)
Address : Blk 187 Bukit Batok West Avenue 6
#10-51
Singapore 650187
Telephone : (Hp) +65 96259384
Type of Claim : Own Damage Claim
Policy No. : 2070006071
Vehicle No : **SMJ 8296 D**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Jan-20
Engine No : CVK 087120
Chassis No : WAUZZZF46KA112470
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Sep-20
Place of Accident : PIE After BKE Exit (Tuas)

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Estimated Labour Charges for Accident Vehicle SMJ 8296 D

S/N Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	\$ 360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	\$ 280.00
3	TO DISMANTLE AND RENEW REAR BUMPER, REAR BUMPER SPOILER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 1,000.00
4	TO RESPRAY REAR BUMPER, REAR LID AND HINGES.	\$ 2,200.00	\$ 1,100.00
5	SUPPLEMENTARY	\$ 1,600.00	\$ 800.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 6,732.00	\$ 3,732.00

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Material List for Accident Vehicle Regn No. SMJ 8296 D

S/N Parts Description		<u>Damage Parts & Prices</u>		
		S/Nett	Remarks	
1	REAR BUMPER	\$ 2,698.00	\$	2,158.40
2	REAR BUMPER FIXING PARTS	\$ 454.00		
3	REAR BUMPER SECURING STRIP	\$ 220.00	\$	176.00
4	REAR BUMPER SPOILER	\$ 246.00	\$	196.40
5	REAR BUMPER TRIM	\$ 289.00	\$	230.80
6	REAR BUMPER BRACKET - LH / RH	2 \$ 230.00		
7	REAR LIGHT REFLECTOR - LH / RH	2 \$ 82.00		
8	REAR BUMPER CARRIER	\$ 1,002.00	\$	801.60
9	REAR BUMPER CARRIER SEAL	2 \$ 28.00	\$	22.08
10	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 44.00		
11	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 164.00		
12	REAR PARKING AID SENSOR - INNER / OUTER	2 TBC		
13	REAR PARKING AID SEAL RING	4 \$ 14.00		
14	BOOT LID CONTROL UNIT	\$ 399.00		
15	REAR LID	\$ 2,623.00	\$	2,098.40
16	REAR LID HINGE - LH / RH	2 \$ 452.00		
17	REAR LID LOCK	\$ 227.00		
18	REAR LID ATTACHMENT PARTS	\$ 144.00		
19	REAR LID LOCK STRIKER	\$ 33.00		
20	REAR LID FLAP GASKET	\$ 203.00		
SUB TOTAL SPARE PARTS CHARGES		\$ 9,552.00	\$	5,683.68



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Material List for Accident Vehicle Regn No. SMJ 8296 D

S/N	Parts Description	<u>Damage Parts & Prices</u>		
			S/Nett	Remarks
		<i>c/f</i>		\$ 5,683.68
21	PACKING ADHESIVE	\$	18.00	\$ 14.40
22	AUDI EMBLEM	\$	122.00	\$ 97.60
23	A4 INSCRIPTION	\$	95.00	\$ 75.36
24	REAR CROSS PANEL TRIM	\$	164.00	
25	REAR NUMBER PLATE	S/N \$	60.00	\$ 60.00
26	SUNDRIES	\$	300.00	\$ 2.24
TOTAL SPARE PARTS CHARGES		:	\$ 10,311.00	\$ 5,933.28
TOTAL LABOUR CHARGES		:	\$ 6,732.00	\$ 3,732.00
GRAND TOTAL		:	\$ 17,043.00	\$ 9,665.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0631/2020/NS 5-Oct-20 Glory Tan 1 of 1 SMJ 8296 D Audi A4 Sedan 2.0 TFSI 8W	
Quantity	Description	Unit Price	Amount	
<u>Labours</u>				
1	To repair rear end panelling.	\$ 700.00	\$ 250.00	
2	To respray rear end panelling.	\$ 900.00	\$ 550.00	
TOTAL		\$ 1,600.00	\$800.00	

For Premium Automobiles Pte Ltd

 Authorised Signature



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant