Not Nothonks Resurvey B& paint

AAD2009-051

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5661T

1 COVER, REAR BU 1 GUARD, REAR BU 1 RETAINER, REAR	rer: tion: PART JMPER T SUB-ASSY, REAR BUMPER JMPER, LOWER JMPER, CENTER BUMPER SIDE, RH MPER EXTENSION, RH Y, QUARTER, RH EEL HOUSE, RH	TOTAL 25%	JTE TO PRI 10. ERG 26/ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	9.2020 GO 10/2018 BUST SVC X PU/LA SVC X SL SVC X SL SVC Z SL SL SL 2	442.60 332.70 15.40	X 7 X
	Special Nett		\$	Sa	700.00	X
1SET PARKING AID	TD.		\$	na	75.00	
1 REAR BUMPER CI			\$	Ma	180.00	305h
1 REAR BUMPER PI 1 REAR WHEEL RIM			\$,879.40	
1 REAR BUMPER RE			\$		65.00	
1 Rear Licence Plate			\$		130.00	
1 Rear Fender Liner	Clip		\$		65.00	_X
		TOTAL	\$	3,	,094.40	-
	TOTAL	PARTS	\$	5,	,125.55	_

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2009-051

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5661T

To remove and refit of rear bumper fittings, attachment to facilitate bodywork repair.		N	170.00	×
Putty And Spray Painting Of The Affected Portion.	\$	1	L,200.00	2801
To reinstall rear bumper parking sensor.			170.00	501
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	101
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1	.,200.00	2001
To Rust-Proofing and apply undercoat Of The Affected Areas.		nn	250.00	X
To check steering geometry and computer wheel		nn	220.00	X
alignment	\$	3,	550.00	-
Over All Total	\$	8,	675.55	•
(PART-BY-PART) Repair Days		15 Days 2 day,		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: