

REC BY:

REF: CS/CT1 20002649/ESF3

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO-06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

TEL: 64616555

ATTN: Motor Claim Department

Your Ref No: SJL5903E

Claim Type: Own Damage

Accident Date: 10/09/2020

Estimate No: MC1901396

Date: 11 Sep 2020

Policy No: D19MYPV01015726

Veh Reg No: SJL5903E

Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

12 days

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 FRONT WINDSCREEN		1 PC CM	450.00	✓
2 FRONT WINDSCREEN MOULDING TOP		1 PC MC	30.00	✓
3 FRONT WINDSCREEN MOULDING SIDE - CHECK PRICE		2 PC NIT	0.0000	X
4 FRONT BONNET		1 PC B	300.00	✓
5 FRONT BONNET HINGE LH & RH		2 PC	60.00	✓
6 FRONT BONNET INSULATOR		1 PC	40.00	✓
7 FRONT BONNET INSULATOR CLIPS		10 PC	80.00	✓
8 FRONT BONNET RUBBER SIDE (SMALL) SIDE		2 PC	12.00	✓
9 FRONT BONNET RUBBER INNER		1 PC	10.00	✓
10 FRONT BONNET INNER LOCK		1 PC B	45.00	✓
11 FRONT BONNET CABLE		1 PC TA	30.00	✓
12 HEADLAMP LH & RH		2 PC CM	500.00	✓
13 HEADLAMP LOWER BEAM LH & RH		2 PC B	36.00	✓
14 HEADLAMP HID BULD LH & RH		2 PC	360.00	✓
15 HEADLAMP HID CONTROL UNIT LH & RH		2 PC	440.00	✓
16 FRONT GRILLE		1 PC M/S	60.00	✓
17 FRONT GRILLE EMBLEM		1 PC M	15.00	✓
18 FRONT GRILLE CHROME MOULDING		1 PC M/S	60.00	✓
19 FRONT GRILLE CLIPS		8 PC M	8.00	✓
20 FRONT BUMPER		1 PC B/H CM	180.00	✓
21 FRONT BUMPER SIDE RETAINER LH & RH		2 PC D/S	20.00	✓
22 FRONT BUMPER CLIPS		15 PC M	15.00	✓
23 FRONT BUMPER REINFORCEMENT		1 PC B	155.00	✓
24 FOGLAMP LH & RH		2 PC S	400.00	X
25 FRONT FENDER LH & RH		2 PC	310.00	✓
26 FRONT FENDER COWLING LH & RH		2 PC D/S	96.00	✓
27 FRONT FENDER COWLING CLIPS		16 PC M	16.00	✓
28 FRONT FENDER TOP COVER LH & RH		2 PC M/S	30.00	✓
29 RADIATOR SUPPORT PANEL		1 PC B	340.00	✓
30 RADIATOR SUPPORT PANEL TOP GARNISH		1 PC D/S	35.00	✓
31 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS		8 PC M	8.00	✓
32 AIR CON CONDENSER		1 PC B	350.00	✓
33 AIR CON CONDENSER FAN MOTOR		1 PC T	95.00	✓
34 AIR CON CONDENSER FAN BLADE		1 PC D/S	30.00	✓
35 AIR CON CONDENSER FAN COWLING		1 PC CM	65.00	✓
36 AIR CON CONDENSER PIPE (COND-COMP)		1 PC D/S	110.00	✓
37 AIR CON CONDENSER PIPE (COND-VALVE)		1 PC S	90.00	X
38 AIR CON CONDENSER PIPE (COMP-VALVE)		1 PC S	75.00	X
39 AIR CON CONDENSER TOP BRACKET LH & RH		2 PC D/S	30.00	✓
40 AIR CON CONDENSER BOTTOM BUSH LH & RH		2 PC T	20.00	✓



Not Authored

C/Sing B

Repair After Paint

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

ATTN: Motor Claim Department

Your Ref No: SJL5903E

Claim Type: Own Damage

Accident Date: 10/09/2020

Estimate No: MC1901396
Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
41 RADIATOR ASSY		1 PC	360.00	✓
42 RADIATOR FAN MOTOR		1 PC	95.00	✓
43 RADIATOR FAN BLADE		1 PC	40.00	✓
44 RADIATOR FAN COWLING		1 PC	65.00	✓
45 RADIATOR TOP HOSE		1 PC	12.00	✓
46 RADIATOR BOTTOM HOSE		1 PC	12.00	✓
47 RADIATOR TOP BRACKET LH & RH		2 PC	30.00	✓
48 RADIATOR TOP BUSH LH & RH		2 PC	16.00	✓
49 RADIATOR BOTTOM BUSH LH & RH		2 PC	20.00	✓
50 RADIATOR SPARE TANK		1 PC	22.00	✓
51 RADIATOR SPARE TANK HOSE (SMALL)		1 PC	18.00	✓
52 RADIATOR CAP BRACKET		1 PC	35.00	x
53 WIPER WASHER TANK		1 PC	50.00	✓
54 WIPER WASHER TANK NECK		1 PC	15.00	x
55 WIPER WASHER TANK MOTOR		1 PC	35.00	x
56 ABS PUMP		1 PC	980.00	✓
57 ALTERNATOR		1 PC	480.00	✓
58 ALTERNATOR BELT		1 PC	45.00	✓
59 INTAKE HEATSHIELD TOP - CHECK PRICE		1 PC	0.0000	✓
60 INTAKE HEATSHIELD LOWER - CHECK PRICE		1 PC	0.0000	✓
61 AIR DUCT OUTER		1 PC	35.00	✓
62 AIR FILTER BOX TOP		1 PC	25.00	x
63 AIR FILTER BOX LOWER		1 PC	35.00	✓
64 BATTERY COVER		1 PC	10.00	✓
65 BATTERY TRAY		1 PC	15.00	✓
66 BATTERY LOWER BRACKET		1 PC	35.00	x
67 ENGINE ECU		1 PC	1,637.70	✓
68 ENGINE UNDER COVER		1 PC	45.00	x
69 ENGINE UNDER COVER CLIPS		10 PC	10.00	x
70 ENGINE MOUNTING TOP		1 PC	70.00	✓
71 ENGINE MOUNTING RH		1 PC	135.00	✓
72 ENGINE MOUNTING REAR		1 PC	70.00	✓
73 GEARBOX MOUNTING LH		1 PC	90.00	✓
74 FRONT HWEELHOUSE PANEL RH		1 PC	250.00	✓
75 AIRBAG SENSOR		2 PC	170.00	✓
76 AIRBAG ECU		1 PC	460.00	✓
77 DASHBOARD ASSY		1 PC	480.00	✓
78 DASHBOARD AIRBAG LH		1 PC	650.00	✓
79 DASHBOARD AIRBAG COVER LH		1 PC	200.00	✓
80 STEERING WHEEL AIR BAG		1 PC	750.00	✓
81 STEERING WHEEL AIR BAG CONTACT RING		1 PC	351.20	✓

25/11/2020 @ 10:05AM CHECKED
WITH KENNETH THE CONDITION

SVC X



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

Estimate No: MC1901396
Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
82 FRONT SEAT BELT LH & RH		2 PC	660.00	✓
			13,519.90	
	Add 10%		1,351.99	14,871.89

Special Nett

- 83 NUMBER PLATE
- 84 RADIATOR COOLANT
- 85 POWER STEERING FLUID
- 86 INNER SEAL
- 87 WINDSCREEN SEALANT
- 88 BATTERY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1 PC	35.00	✓
1 PC	30.00	✓
1 PC	50.00	✓
1 PC	20.00	✓
1 PC	40.00	✓
1 PC	180.00	✓
		355.00

LABOUR

- 89 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.
- 90 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.
- 91 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.
- 92 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.
- 93 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.
- 94 TO DISMANTLE AND INSTALL STEERING WHEEL AIR-BAG, PASSENGER AIR-BAG, SEATBELTS AND AIR-BAG CONTROL BOX.
- 95 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT
- 96 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL, FRT WHEELHOUSE PANEL RH TO KNOCK & REPAIR FRT WHEELHOUSE PANEL LH, FRT CHASSIS LH & RH, FRT DOOR LH & RH, FRT DOOR PILLAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.
- 97 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR LH & RH, FRT DOOR PILLAR LH & RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH, FRONT WHEELHOSUE LH & RH.

1 PC	40.00	301
1 PC	100.00	✓
1 PC	80.00	601
1 PC	120.00	✓
1 PC	280.00	2501
1 PC	150.00	✓
1 PC	250.00	✓
1 PC	1,600.00	11001
1 PC	1,600.00	12801

4,220.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

Estimate No: MC1901396
Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Lump Sum Repair	S\$ 19,446.89 19,743.89
Add GST @ 7%	1,361.28
Total Amount payable	S\$ 20,808.17

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND EIGHT HUNDRED AND EIGHT AND CENTS SEVENTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

Estimate No: MC1901396
Date: 29 Oct 2020
Policy No: D19MTPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
SPARE PARTS				
1 EGR PIPE DD ✓		1 PC	90.00	
2 O2 SENSOR DD ✓		1 PC	180.00	
			270.00	
		Add 10%	27.00	297.00
Lump Sum Repair				S\$ 297.00
GST Amount				S\$ 20.79
Total Amount payable				S\$ 317.79

The above vehicle was surveyed by KENNETH KONG -LKK on 11/09/2020

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE