

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

SURVEYOR COPY

Estimate No: MC1901396
Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT WINDSCREEN		1 PC	450.00	
2 FRONT WINDSCREEN MOULDING TOP		1 PC	30.00	
3 FRONT WINDSCREEN MOULDING SIDE - CHECK PRICE		2 PC	0.0000	
4 FRONT BONNET		1 PC	300.00	
5 FRONT BONNET HINGE LH & RH		2 PC	60.00	
6 FRONT BONNET INSULATOR		1 PC	40.00	
7 FRONT BONNET INSULATOR CLIPS		10 PC	80.00	
8 FRONT BONNET RUBBER SIDE (SMALL) SIDE		2 PC	12.00	
9 FRONT BONNET RUBBER INNER		1 PC	10.00	
10 FRONT BONNET INNER LOCK		1 PC	45.00	
11 FRONT BONNET CABLE		1 PC	30.00	
12 HEADLAMP LH & RH		2 PC	500.00	
13 HEADLAMP LOWER BEAM LH & RH		2 PC	36.00	
14 HEADLAMP HID BULD LH & RH		2 PC	360.00	
15 HEADLAMP HID CONTROL UNIT LH & RH		2 PC	440.00	
16 FRONT GRILLE		1 PC	60.00	
17 FRONT GRILLE EMBLEM		1 PC	15.00	
18 FRONT GRILLE CHROME MOULDING		1 PC	60.00	
19 FRONT GRILLE CLIPS		8 PC	8.00	
20 FRONT BUMPER		1 PC	180.00	
21 FRONT BUMPER SIDE RETAINER LH & RH		2 PC	20.00	
22 FRONT BUMPER CLIPS		15 PC	15.00	
23 FRONT BUMPER REINFORCEMENT		1 PC	155.00	
24 FOGLAMP LH & RH		2 PC	400.00	
25 FRONT FENDER LH & RH		2 PC	310.00	
26 FRONT FENDER COWLING LH & RH		2 PC	96.00	
27 FRONT FENDER COWLING CLIPS		16 PC	16.00	
28 FRONT FENDER TOP COVER LH & RH		2 PC	30.00	
29 RADIATOR SUPPORT PANEL		1 PC	340.00	
30 RADIATOR SUPPORT PANEL TOP GARNISH		1 PC	35.00	
31 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS		8 PC	8.00	
32 AIR CON CONDENSER		1 PC	350.00	
33 AIR CON CONDENSER FAN MOTOR		1 PC	95.00	
34 AIR CON CONDENSER FAN BLADE		1 PC	30.00	
35 AIR CON CONDENSER FAN COWLING		1 PC	65.00	
36 AIR CON CONDENSER PIPE (COND-COMP)		1 PC	110.00	
37 AIR CON CONDENSER PIPE (COND-VALVE)		1 PC	90.00	
38 AIR CON CONDENSER PIPE (COMP-VALVE)		1 PC	75.00	
39 AIR CON CONDENSER TOP BRACKET LH & RH		2 PC	30.00	
40 AIR CON CONDENSER BOTTOM BUSH LH & RH		2 PC	20.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

SURVEYOR COPY
Estimate No: MC1901396

Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
41 RADIATOR ASSY		1 PC	360.00	
42 RADIATOR FAN MOTOR		1 PC	95.00	
43 RADIATOR FAN BLADE		1 PC	40.00	
44 RADIATOR FAN COWLING		1 PC	65.00	
45 RADIATOR TOP HOSE		1 PC	12.00	
46 RADIATOR BOTTOM HOSE		1 PC	12.00	
47 RADIATOR TOP BRACKET LH & RH		2 PC	30.00	
48 RADIATOR TOP BUSH LH & RH		2 PC	16.00	
49 RADIATOR BOTTOM BUSH LH & RH		2 PC	20.00	
50 RADIATOR SPARE TANK		1 PC	22.00	
51 RADIATOR SPARE TANK HOSE (SMALL)		1 PC	18.00	
52 RADIATOR CAP BRACKET		1 PC	35.00	
53 WIPER WASHER TANK		1 PC	50.00	
54 WIPER WASHER TANK NECK		1 PC	15.00	
55 WIPER WASHER TANK MOTOR		1 PC	35.00	
56 ABS PUMP		1 PC	980.00	
57 ALTERNATOR		1 PC	480.00	
58 ALTERNATOR BELT		1 PC	45.00	
59 INTAKE HEATSHIELD TOP - CHECK PRICE		1 PC	0.0000	
60 INTAKE HEATSHIELD LOWER - CHECK PRICE		1 PC	0.0000	
61 AIR DUCT OUTER		1 PC	35.00	
62 AIR FILTER BOX TOP		1 PC	25.00	
63 AIR FILTER BOX LOWER		1 PC	35.00	
64 BATTERY COVER		1 PC	10.00	
65 BATTERY TRAY		1 PC	15.00	
66 BATTERY LOWER BRACKET		1 PC	35.00	
67 ENGINE ECU		1 PC	1,637.70	
68 ENGINE UNDER COVER		1 PC	45.00	
69 ENGINE UNDER COVER CLIPS		10 PC	10.00	
70 ENGINE MOUNTING TOP		1 PC	70.00	
71 ENGINE MOUNTING RH		1 PC	135.00	
72 ENGINE MOUNTING REAR		1 PC	70.00	
73 GEARBOX MOUNTING LH		1 PC	90.00	
74 FRONT HWEELHOUSE PANEL RH		1 PC	250.00	
75 AIRBAG SENSOR		2 PC	170.00	
76 AIRBAG ECU		1 PC	460.00	
77 DASHBOARD ASSY		1 PC	480.00	
78 DASHBOARD AIRBAG LH		1 PC	650.00	
79 DASHBOARD AIRBAG COVER LH		1 PC	200.00	
80 STEERING WHEEL AIR BAG		1 PC	750.00	
81 STEERING WHEEL AIR BAG CONTACT RING		1 PC	351.20	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department
Your Ref No: SJL5903E
Claim Type: Own Damage
Accident Date: 10/09/2020

Estimate No: MC1901396
Date: 11 Sep 2020
Policy No: D19MYPV01015726
Veh Reg No: SJL5903E
Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
82 FRONT SEAT BELT LH & RH		2 PC	660.00	
			13,519.90	
	Add 10%		1,351.99	14,871.89
Special Nett				
83 NUMBER PLATE		1 PC	35.00	
84 RADIATOR COOLANT		1 PC	30.00	
85 POWER STEERING FLUID		1 PC	50.00	
86 INNER SEAL		1 PC	20.00	
87 WINDSCREEN SEALANT		1 PC	40.00	
88 BATTERY		1 PC	180.00	
				355.00
LABOUR				
89 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	
90 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
91 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	
92 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		1 PC	120.00	
93 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.		1 PC	280.00	
94 TO DISMANTLE AND INSTALL STEERING WHEEL AIR-BAG, PASSENGER AIR-BAG, SEATBELTS AND AIR-BAG CONTROL BOX.		1 PC	150.00	
95 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	250.00	
96 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,FRT WHEELHOUSE PANEL RH.TO KNOCK & REPAIR FRT WHEELHOUSE PANEL LH,FRT CHASSIS LH & RH, FRT DOOR LH & RH,FRT DOOR PILLAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,600.00	
97 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FEDNER LH & RH,FRONT DOOR LH & RH,FRT DOOR PILLAR LH & RH,RADIATOR SUPPORT PANEL, FRONT CHASSIS LH & RH,FRONT WHEELHOSUE LH & RH.		1 PC	1,600.00	
				4,220.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

ATTN: Motor Claim Department

Your Ref No: SJL5903E

Claim Type: Own Damage

Accident Date: 10/09/2020

Estimate No: MC1901396

Date: 11 Sep 2020

Policy No: D19MYPV01015726

Veh Reg No: SJL5903E

Make/Model: HONDA CIVIC 1.8L 5AT

Estimate Repair Cost to Vehicle No : SJL5903E

Lump Sum Repair S\$ 19,446.89

Add GST @ 7% 1,361.28

Total Amount payable S\$ 20,808.17

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND EIGHT HUNDRED AND EIGHT AND CENTS SEVENTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 825H

Vehicle Details

Vehicle No.: SJL5903E
Vehicle to be Exported: No
Intended Deregistration Date: 10 Sep 2020
Vehicle Make: HONDA
Vehicle Model: HONDA CIVIC 1.8L 5AT
Primary Colour: Brown
Manufacturing Year: 2008
Engine No.: R18A14009508
Chassis No.: JHMF16309S201622
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$25,978.00
Original Registration Date: 03 Dec 2008
First Registration Date: 03 Dec 2008
Transfer Count: 1
Actual ARF Paid: \$25,978.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 02 Dec 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$15,777.00
COE Rebate Amount: \$10,184.00
Total Rebate Amount: \$10,184.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Sep 2020

OK