

DATE : 11.09.20

Asher.
GEG1104414

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>distorted</i>	1	\$ 849.90	\$ 849.90
2	TAIL GATE OUTER HANDLE <i>cracked</i>	1	\$ 164.90	\$ 164.90
3	TAIL GATE LOGO <i>new</i>	1	\$ 24.70	\$ 24.70
4	TAIL GATE EMBLEM "FIT" <i>new</i>	1	\$ 28.80	\$ 28.80
5	TAIL GATE 3RD BRAKE LIGHT <i>new</i>	1	\$ 191.00	\$ 191.00
6	TAIL GATE WINDSCREEN <i>shattered</i>	1	\$ 675.60	\$ 675.60
7	TAIL GATE WINDSCREEN MOULDING <i>new</i>	2	\$ 76.00	\$ 152.00
8	TAIL GATE WIPER ARM <i>new</i>	1	\$ 69.80	\$ 69.80
9	TAIL GATE WIPER ARM BOLT COVER <i>new</i>	1	\$ 42.10	\$ 42.10
10	TAIL GATE WIPER MOTOR <i>new</i>	1	\$ 436.30	\$ 436.30
11	TAIL GATE NUMBER PLATE LAMP <i>new</i>	2	\$ 45.00	\$ 90.00
12	TAIL GATE DAMPER <i>3 new</i>	2	\$ 194.40	\$ 388.80
13	TAIL GATE HINGE	2	\$ 42.00	\$ 84.00
14	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 47.10	\$ 47.10
15	TAIL GATE STOPPER <i>new</i>	2	\$ 12.00	\$ 24.00
16	TAIL GATE INNER LOCK <i>Turned</i>	1	\$ 169.40	\$ 169.40
17	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 25.00	\$ 25.00
18	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 134.50	\$ 134.50
19	TAIL GATE INNER TRIM <i>cracked</i>	1	\$ 372.20	\$ 372.20
20	TAIL GATE WIRE HARNESS <i>new</i>	1	\$ 899.60	\$ 899.60
21	TAIL LAMP <i>LH smashed, RH cracked</i>	2	\$ 296.10	\$ 592.20
22	TAIL LAMP PANEL (OUTER) <i>LH cracked</i>	2	\$ 168.30	\$ 336.60
23	TAIL LAMP INNER PANEL (UPPER) <i>3 pieces</i>	2	\$ 296.60	\$ 593.20
24	TAIL LAMP INNER PANEL (LOWER)	2	\$ 284.70	\$ 569.40
25	REAR FENDER <i>LH Buckled</i>	2	\$ 677.80	\$ 1,355.60
26	REAR FENDER INNER COWLING <i>to be</i>	2	\$ 78.10	\$ 156.20
27	REAR FENDER INNER TRIM <i>cracked</i>	2	\$ 298.90	\$ 597.80
28	REAR FENDER INNER UPPER TRIM <i>new</i>	2	\$ 189.60	\$ 379.20

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJM7143M**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 10.09.20
 TIME OF ACCIDENT : 18:15HRS

29	REAR FENDER INNER PANEL LH <i>Regr</i>	1	\$ 764.20	\$ 764.20	+
30	REAR WHEEL HOUSE PANEL <i>Regr</i>	2	\$ 997.70	\$ 1,995.40	+
31	REAR WHEEL HOUSE UPPER PANEL <i>Regr</i>	2	\$ 439.80	\$ 879.60	+
32	REAR FENDER AIR VENT <i>Regr</i>	2	\$ 72.30	\$ 144.60	+
33	REAR QUATER GLASS INNER PANEL LH <i>Regr</i>	1	\$ 455.70	\$ 455.70	+
34	REAR QUATER GLASS C/W MOULDING <i>alt</i>	2	\$ 280.00	\$ 560.00	SS
35	REAR FUEL TANK PANEL <i>Regr</i>	1	\$ 89.60	\$ 89.60	+
36	REAR DOOR <i>Regr</i>	2	\$ 896.80	\$ 1,793.60	+
37	REAR DOOR WEATHERSTRIP <i>Regr</i>	2	\$ 175.60	\$ 351.20	+
38	REAR DOOR INNER LOCK <i>Regr</i>	2	\$ 283.00	\$ 566.00	+
39	REAR DOOR INNER TRIM <i>Regr</i>	2	\$ 797.00	\$ 1,594.00	+
40	REAR DOOR WEATHERSTRIP <i>Regr</i>	2	\$ 154.60	\$ 309.20	+
41	REAR END PANEL <i>Distorted</i>	1	\$ 356.70	\$ 356.70	✓
42	REAR END PANEL TOP GARNISH <i>anked</i>	1	\$ 116.20	\$ 116.20	✓
43	REAR FLOOR PANEL <i>Distorted</i>	1	\$ 1,147.70	\$ 1,147.70	737
44	REAR FLOOR PANEL TOP BOARD <i>Regr</i>	1	\$ 185.60	\$ 185.60	✓
45	REAR TOOLS BOX <i>Regr</i>	1	\$ 294.20	\$ 294.20	✓
46	REAR CHASSIS FRAME LH <i>Regr</i>	1	\$ 798.80	\$ 798.80	+
47	REAR CHASSIS TOP PANEL <i>Regr</i>	2	\$ 196.10	\$ 392.20	✓
48	REAR TOWING HOOK PANEL <i>Regr</i>	1	\$ 323.20	\$ 323.20	+
49	CENTER EXHAUST <i>Regr</i>	1	\$ 769.30	\$ 769.30	+
50	CENTER EXHAUST INSULATOR <i>Regr</i>	1	\$ 49.80	\$ 49.80	+
51	CENTER EXHAUST GASKET (SET) <i>Regr</i>	1	\$ 60.00	\$ 60.00	+
52	REAR EXHAUST INSULATOR <i>Regr</i>	1	\$ 58.40	\$ 58.40	+
53	REAR EXHAUST GASKET (SET) <i>Regr</i>	1	\$ 60.00	\$ 60.00	+
54	FRONT SEAT RH <i>Regr</i>	1	\$ 1,684.00	\$ 1,684.00	+

7410.90 TOTAL PRICE \$ 25,165.10
 5928.72 LESS 20% \$ 5,033.02
 SUB TOTAL PRICE \$ 20,132.08

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Regr</i>	1	\$ 80.00	\$ 80.00	450
2	REAR BUMPER CLIP (SET) <i>Regr</i>	1	\$ 50.00	\$ 50.00	30
3	REAR BUMPER (SPECIAL TYPE) <i>Distorted</i>	1	\$ 1,800.00	\$ 1,800.00	800
4	TAIL GATE EMBLEM " MUGEN" (SPECIAL TYPE) <i>Regr</i>	1	\$ 150.00	\$ 150.00	75
5	TAILGATE SPOILER (SPECIAL TYPE) <i>anked</i>	1	\$ 1,800.00	\$ 1,800.00	750
6	TAIL GATE WINDSCREEN SEALANT <i>Regr</i>	1	\$ 80.00	\$ 80.00	40
7	TAIL GATE WINDSCREEN INNER SEAL <i>Regr</i>	1	\$ 60.00	\$ 60.00	40

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJM7143M**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 10.09.20
 TIME OF ACCIDENT : 18:15HRS

8	TAIL GATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 550.00	\$ 550.00	<i>20</i>
9	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>20</i>
10	TAIL LAMP PANEL (OUTER) SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	<i>30</i>
11	REAR FENDER SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	<i>50</i>
12	REAR FENDER INNER COWLING (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>-</i>
13	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>60</i>
14	REAR WHEEL HOUSE PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
15	REAR QUATER GLASS SEALANT LH <i>new</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
16	REAR QUATER GLASS INNER SEAL LH <i>new</i>	1	\$ 40.00	\$ 40.00	<i>20</i>
17	REAR QUATER GLASS SOLAR FILM LH <i>new</i>	1	\$ 180.00	\$ 180.00	<i>x</i>
18	REAR SHOCK ABSORBER (SET)(SPECIAL TYPE) <i>new</i>	1	\$ 1,600.00	\$ 1,600.00	<i>x</i>
19	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
20	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
21	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	<i>x</i>
22	REAR CHASSIS TOP PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>30</i>
23	ROOF LINING CLIP (SET) <i>new</i>	1	\$ 180.00	\$ 180.00	<i>x</i>
24	REAR EXHAUST PIPE (SPECIAL TYPE) <i>Dented</i>	1	\$ 2,200.00	\$ 2,200.00	<i>1000</i>
25	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>
26	VIDEO RECORDER <i>Damaged</i>	1	\$ 680.00	\$ 680.00	<i>400</i>
			TOTAL	\$ 10,980.00	<i>3945</i>

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,800.00	<i>1600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>1400</i>
3	TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 550.00	<i>200</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	<i>50</i>
8	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>x</i>

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SJM7143M
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 10.09.20
 TIME OF ACCIDENT : 18:15HRS

9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	CONDUCT WATER LEAKAGE TEST	\$ 180.00	x
12	REMOVE AND REFIX REAR FENDER GLASS LH	\$ 100.00	60
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 100.00	80
14	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	x
15	FOUR WHEEL ALIGNMENT	\$ 120.00	x
16	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
17	VACUUM AND CLEAN REAR WINDSCREEN GLASS SPLINTER	\$ 220.00	60
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

3930

TOTAL \$8,120.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 31,312.08
 TOTAL LABOUR COST : \$ 8,120.00
 TOTAL REPAIR COST : \$ 39,432.08

39,299.28#

Adrian L
 L/S 14/09/20
 13 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 1380372
 L/S: 11K
 13 Days