



Section A - Accident Details

Registration Number	SHC4655Z
Case Reference Number	TAX/09/20/2021
Registration Date	19/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHAN KIN WHYE
Type of Accident	Head To Side
Accident Date and Time	8/9/2020 11:23 AM
Accident Reported Date and Time	8/9/2020 1:24 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108094
Special Instruction to ARC, if any	LEFT PORTION
Prepared Date and Time	8/9/2020 3:58 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$1,854.00	\$550.00
Total Spare Part Cost	\$8,384.42	\$2,657.19
Total Other Cost	\$1,735.00	\$375.00
TOTAL COST	\$12,987.42	\$4,182.19
Lump Sum Total	\$13,000.00	\$4,200.00 (L/S)
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	11/09/2020 11:05 AM	11/09/2020 10:50 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	L/S, after paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2009-0340	Invoice Number	
Quotation Date	23.09.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY SILL MEMBER LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR LH WHEEL HOUSE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,854.00	\$550.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE & REFIT FUEL TANK	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE AND REFIT UNDERCARRIAGE	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$60.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$180.00	\$0.00
Total Other Costs	\$1,735.00	\$375.00

XRPT.

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75852-47900	MOULDING BODY, LH	1.00	\$673.60	25.00	\$505.20	Replace	Replace
		65632-47041	SILL MEMBER PLATE RR/LH	1.00	\$57.50	25.00	\$43.13	Replace	Replace
		61404-47030	SILL MEMBER OUTER LH	0.00	\$519.80	0.00	\$0.00	Replace	Check

CRU
CRU
SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/09/2020

User ID : PohSuan

67004-47080	DOOR RR/LH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	✓	CRU
68780-52031	HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X	SVC
68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X	SVC
68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	SVC
	PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓	NEC
75740-47021	DOOR BELT RR/LH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given	X	SVC
69060-47080	DOOR LOCK RR/LH	0.00	\$709.30	0.00	\$0.00	Replace	Not Given	X	SVC
69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Not Given	X	SVC
67640-47260	DOOR REAR LH TRIM BOARD	0.00	\$590.10	0.00	\$0.00	Replace	Not Given	X	SVC
67872-47030	DOOR WEATHER STRIP RR/LH	0.00	\$171.20	0.00	\$0.00	Replace	Check	X	SVC
62332-47030-C0	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	0.00	\$249.80	0.00	\$0.00	Replace	Check	X	SVC
61602-47091	FENDER RR/LH	1.00	\$766.80	25.00	\$575.10	Replace	Replace	✓	CRU
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓	NEC
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓	NEC
65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X	SVC
62720-47031	QUARTER GLASS RR/LH	1.00	\$168.10	25.00	\$126.08	Replace	Replace	✓	NEC
	SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	✓	NEC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
42611-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	✓	
42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X	SVC
42101-12171	REAR CROSS MEMBER	0.00	\$2,621.50	0.00	\$0.00	Replace	Not Given	X	SVC
48530-80533	SHOCK ABSORBER REAR	0.00	\$112.30	0.00	\$0.00	Replace	Not Given	X	SVC
48725-47030	BUSH, RR CROSS MEMBER	0.00	\$148.50	0.00	\$0.00	Replace	Not Given	X	SVC
61606-47010	PANEL, QUARTER WHEEL HOUSE, OUTER LH	0.00	\$326.70	0.00	\$0.00	Replace	Not Given	X	SVC
77201-47250	PIPE SUB-ASSY, FUEL NECK	0.00	\$230.80	0.00	\$0.00	Replace	Not Given	X	SVC
77226-47040	TUBE, FUEL TANK	0.00	\$36.10	0.00	\$0.00	Replace	Not Given	X	SVC
67918-47041	SCUFF PLATE, RR DOOR LH	0.00	\$153.20	0.00	\$0.00	Replace	Not Given	X	SVC
67916-47020	SCUFF STEP PLATE LH,RR DR	0.00	\$107.49	0.00	\$0.00	Replace	Not Given	X	SVC
52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given	X	SVC
52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X	SVC
52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X	SVC
	PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X	SVC
Total			\$12,081.53		\$2,091.79				

CRU
SVC
SVC
SVC
NEC
SVC
SVC
SVC
SVC
SVC
CRU
NEC
NEC
SVC
NEC
NEC
SVC

4S
\$4,200
4 days

3,321.49
- 20%
2,657.19
600
925
4,182.19

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace
		67872-47030	DOOR WEATHER STRIP RR/LH	1.00	\$171.20	25.00	\$128.40	Replace	Replace
		67640-47260	DOOR REAR LH TRIM BOARD	1.00	\$590.10	25.00	\$442.58	Replace	Replace
		69060-47080	DOOR LOCK RR/LH	1.00	\$709.30	25.00	\$531.98	Replace	Replace
Total					1,597.34		1,229.70		

C44
CRU
CRA
CRA