




Accident Photo



Accident Photo



Accident Photo



Accident Photo



FINAL REPAIR BILL

WEE AUTO SERVICE

Business Reg No: 53206799A

19 Kim Chuan Terrace Singapore 537041

Tel: 6858 0019 Fax: 6858 6470 Tow: 9666 5566

India International Insurance Pte. Ltd.

64 Cecil Street

#04/06-00 IOB Building

Singapore 049711

Attn: Motor Claims Department

Invoice No: WA20-013

Claims No: T/P Claim

Date: 23-Mar-20

Our Car No: SJW4189Z

Your Car No: SHB4345Z

Description

Amount (S\$)

Supply of parts, labour charges and spray painting

9,880.00

Total:

9,880.00

Singapore Dollars Nine Thousand Eight Hundred Eighty

Crossed cheques should be made payable to "Wee Auto Service" and mailed to 19 Kim Chuan Terrace S(537041)

WEE AUTO SERVICE
Business Regn: 53206799A
19 Kim Chuan Terrace
Singapore 537041
Tel: 6858 0019

Authorised signatory



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529690)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

INVOICE

M/s. Chang Zheng Auto Agency
C/o. 19 Kim Chuan Terrace
Singapore 537041

Invoice No. : HA/2002-37

Date : 21/02/2020


Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 574.00
SGD Dollar : Five Hundred Seventy Four Dollars Only.	
Our Reference : PAS/TP/0100120	
Vehicle No. : SJW4189Z	
Make & Model : Toyota Corolla Altis	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0100120

Date of Report : 21/02/2020

To : M/s. Chang Zheng Auto Agency
C/o. 19 Kim Chuan Terrace
Singapore 537041

Date of Assignment : 07/01/2020
Report requested by : M/s. Chang Zheng Auto Ager
Date of Accident : 04/01/2020
Date of Inspection : 07/01/2020
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SJW4189Z
Make & Model : Toyota Corolla Altis
Date of Registration : 17/03/2009
Colour : Met. Blue

Engine Capacity (cc) : 1598cc
Mileage (km) : 243904km
Chassis / Frame No. : MR053ZEE106141348
Engine No. : 3ZZ4869511

TYRE CONDITION

Front LH : 7 mm
Make : CST Tires

Front RH : 7 mm
Make : CST Tires

Rear LH : 7 mm
Make : CST Tires

Rear RH : 7 mm
Make : CST Tires

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Wee Hoe Auto Service
19, Kim Chuan Terrace, Singapore 537041

ASSESSMENT

Repairer's Estimate : \$ 13,967.38
Revised Amount : \$ 12,350.20
Less Excess : \$ -
Recommended Reserve : \$ 9,880.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJW4189Z

Report No. : PAS/TP/0100120

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Wee Hoe Auto Service, 19, Kim Chuan Terrace, Singapore 537041.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The bonnet, front bumper, front support panel, front chassis members, front fenders, RHF apron panel, RHF wheel house, radiator assy, a/c condenser, headlamps, front grilles, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$12,350.20.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,880.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simel St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJW4189Z

Report No. : PAS/TP/0100120

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	1 pc	Bonnet	Dented		\$ 853.20	\$ 853.20
2	1 pc	Bonnet seal	Torn/Necessary		\$ 59.60	\$ 59.60
3	1 pc	Bonnet insulator	Refit		\$ 266.40	\$ -
4	7 pcs	Bonnet insulator clip	Necessary	\$ 2.50	\$ 17.50	\$ 17.50
5	2 pcs	Bonnet hinge R/L	Bent	\$ 59.70	\$ 119.40	\$ 119.40
6	1 pc	Frt support panel	Dented		\$ 715.30	\$ 715.30
7	1 pc	Frt support brace panel	Dented/Bent		\$ 114.30	\$ 114.30
8	1 pc	Bonnet lock	Dented/Jammed		\$ 129.30	\$ 129.30
9	2 pcs	Headlamp R/L	Cracked/Broken	\$ 708.40	\$ 1,416.80	\$ 1,416.80
10	1 pc	Frt bumper	Dented		\$ 458.40	\$ 458.40
11	1 pc	Frt grille	Dented/Cracked		\$ 301.90	\$ 301.90
12	1 pc	Frt grille emblem	Necessary		\$ 71.00	\$ 71.00
13	1 pc	Frt bumper lower grille	Cracked		\$ 147.10	\$ 147.10
14	6 pcs	Frt bumper clip	Necessary	\$ 3.50	\$ 21.00	\$ 21.00
15	2 pcs	Frt bumper retainer R/L	Cracked/Necessary	\$ 54.60	\$ 109.20	\$ 109.20
16	1 pc	Frt bumper reinforcement	Dented		\$ 341.10	\$ 341.10
17	2 pcs	Frt bumper arm R/L	Dented	\$ 18.60	\$ 37.20	\$ 37.20
18	1 pc	Frt bumper top seal	Torn/Necessary		\$ 51.90	\$ 51.90
19	2 pcs	Frt fog lamp R/L	Refit	\$ 238.40	\$ 476.80	\$ -
20	2 pcs	Frt fog lamp cover R/L	Refit	\$ 61.50	\$ 123.00	\$ -
21	2 pcs	Frt fender R/L	Dented/Distorted	\$ 616.90	\$ 1,233.80	\$ 1,233.80
22	2 pcs	Frt fender cowling R/L	Torn/Deformed	\$ 169.20	\$ 338.40	\$ 338.40
23	12 pcs	Frt fender cowling clip R/L	Necessary	\$ 3.20	\$ 38.40	\$ 38.40
24	2 pcs	Frt fender emblem (VVTi) R/L	Necessary	\$ 41.70	\$ 83.40	\$ 83.40
25	1 pc	Frt apron panel RH	Dented/Distorted		\$ 491.20	\$ 491.20
26	1 pc	Radiator	Dented		\$ 1,965.80	\$ 1,965.80
27	1 pc	Radiator top bracket	Dented/Broken		\$ 96.30	\$ 96.30
28	1 pc	Radiator cooling fan blade	Dented/Cracked		\$ 147.20	\$ 147.20
29	1 pc	Radiator cooling fan motor	Dented/Damaged		\$ 537.90	\$ 537.90
30	1 pc	Radiator cooling fan cowling	Dented/Broken		\$ 83.40	\$ 83.40
31	1 pc	Radiator reserve tank	Refit		\$ 155.60	\$ -
32	1 pc	A/c condenser	Dented		\$ 1,473.60	\$ 1,473.60
33	1 pc	A/c suction pipe	Refit		\$ 132.90	\$ -
34	1 pc	A/c discharge pipe	Refit		\$ 248.30	\$ -
35	1 pc	A/c liquid pipe	Dented/Bent		\$ 236.60	\$ 236.60
36	1 pc	Horn	Dented/Damaged		\$ 63.40	\$ 63.40
37	1 pc	Washer tank	Refit		\$ 119.90	\$ -
38	1 pc	Frt wheel house RH	Dented/Repair		(Refer labour no. 5, 6 & 7)	
39	1 pc	Frt chassis member R/L	Dented/Repair		(Refer labour no. 5, 6 & 7)	
40	1 pc	Frt door RH	Dented/Repair		(Refer labour no. 6 & 7)	
					\$ 13,276.50	\$ 11,753.60
Less Discount : 25%					\$ 3,319.13	25% \$ 2,938.40
List Parts Sub-Total :					\$ 9,957.38	\$ 8,815.20
1	1 set	Frt no.plate (w/bracket)	Dented/Cracked	S/N	\$ 50.00	\$ 50.00
2	1 bot	Radiator coolant	Necessary	S/N	\$ 60.00	\$ 60.00
3	1 pc	Frt apron panel sealant RH	Necessary	S/N	\$ 50.00	\$ 40.00
Parts Total :					\$ 10,117.38	\$ 8,965.20



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJW4189Z

Report No. : PAS/TP/0100120

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	Towing.	\$ 100.00	\$ 85.00
2	To check electrical system, repair wire harness and focus headlamp.	\$ 60.00	\$ 50.00
3	To remove, replace and reinstall a/c condenser & a/c pipings. (Include vacuum & recharge a/c gas)	\$ 120.00	\$ 120.00
4	To remove, replace and reinstall radiator & cooling system. (Include pressure test cooling system)	\$ 100.00	\$ 80.00
5	To conduct chassis alignments.	\$ 320.00	\$ 300.00
6	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,500.00	\$ 1,320.00
7	To spray painting, blending on affected and adjacent area.	\$ 1,600.00	\$ 1,400.00
8	To spray anti-rust coating on new and affected panels.	\$ 50.00	\$ 30.00
Labour Total :		<u>\$ 3,850.00</u>	<u>\$ 3,385.00</u>
Total (Parts & Labour) :		<u>\$ 13,967.38</u>	<u>\$ 12,350.20</u>

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,880.00

Under normal circumstances, the repairs should be completed within a reasonable period of **10 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

64 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.



