

ASS. REC. BY:

REF:

Hennery 012 / 20009741/KV

ASSIGNMENT

Front: _____ Date: _____
 Estimated Cost: _____
OD/PAWS/LTP RES/OD RES/EVA/INV/ MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of Cheng Hoe
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____
 (Client's Record)
 Make of Veh: _____
 Excess: _____

Veh No: SKV 649R Yr Regn: 09, 15
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Toy Priv A c.c. 1897
 Colour: M. Red A/C: Insured / Std / NI / NA
 Sp. Reading: 74528 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/N: JTDKD3B3701101634
 Gen. Condi: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NI / S/R/Im / STD / Burnt or

Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>8</u> mm	R/Bal. <u>8</u> mm
L/Bal. _____ mm	L/Bal. _____ mm
D.O.A. <u>2918120</u>	D.O.I. <u>1679/202</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FA d/s
 The U/C / Chassis frame / Body Structure affected due to collision.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 04 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS _____ Vehicle: IN / OUT
 Date: _____ Person Contacted: _____
 Action / Instruction _____

1 EHNT

2918 61 Prop 823504 Central

no. File Pass to?

: Prel. Report

: Final Report

Days Of Repair: _____

no. File Return to?

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$ _____) : S - FS (\$ _____)

: Interview (\$ _____) : F.M.S

: Tech Invs (\$ _____) : Others

: Weekend (\$ _____) : _____

Format:

Sum / I.B.I: (\$ _____)

TOTAL

SKV6419R
TP/dura

PAIR DETAILS

Reference: Version: 1.0 (Last Synchronised: 16 Sep 2020)
 Source: MRM-SG TOYOTA PRIUS C 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
 Qty: 144 Repairer's (Price-denominated Standard List)
 Code: Cheng Hoe Motor Pte Ltd/SKV6419R/16/09/2020 12:09
 Description: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Other Info: Items/values not in reference catalogue are prefixed with an asterisk *

Qty	Part No.	Particulars	%Disc	%Depr	Amount
	*1 PC	FRT RH FENDER	0.00	0.00	*260.00 F
	*1 PC	RH HEADLAMP	0.00	0.00	*980.00 F
	*1 PC	BONNET	0.00	0.00	*290.00 F
	*1 PC	FRT RH FENDER EMBLEM HYBRID	0.00	0.00	*50.00 F
	*1 PC	FRT BUMPER	0.00	0.00	*185.00 F
	*1 PC	FRT BUMPER LOGO	0.00	0.00	*45.00 F
	*6 PCS	FRT BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F
	*1 PC	FRT BUMPER LAMP	0.00	0.00	*85.00 F

Total Parts (S\$) **1,907.00**

Cheng Hoe Motor Pte Ltd/SKV6419R/16/09/2020 12:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

ates on Miscellaneous Items

no new miscellaneous items selected.

ates on Labour

Particulars	Lab. Type	Amount
WORKS		
MOVE & REFIX FRT BUMPER, FOG LAMPS, CENTER LOWER GRILLE, FRT FENDER, GRILLE, HEADLAMP & REALIGN THE SAME	New	550.00
TYPING & RESPRAY ON FRT BUMPER, BONNET, FRT RH FENDER	New	680.00
WAXING	New	30.00
Gross Labour Cost (S\$)		1,260.00

Cheng Hoe Motor Pte Ltd/SKV6419R/16/09/2020 12:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair/spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: