

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2020 <a href="#">Sendback Est</a>	16 Sep 2020 12:09 <b>S\$3,167.00</b>	11 Sep 2020 14:11 <a href="#">Edit Adj Rpt</a>	<b>S\$2,350.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,350.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:	<b>TUNG SHUN PTE LTD</b> , Co. Reg. No.: 197101100G		
Main Claimant:	<b>KUAN KOW KHIANG</b> , ID: S0181981Z		
Vehicle Reg. No.:	<b>SKV6419R</b>	Date of Loss:	29/08/2020 09:00 - :59 [59 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM20D203299/C02/TKL</b>	Policy/Cover Note No.:	DMCVSN30705019044
Vehicle Reg. No. (Insured):	<b>YN6416A</b>	Policy No. (Claimant):	Z20VP05026459
		Excess:	S\$800.00
Repairer:	<b>Cheng Hoe Motor Pte Ltd (Yishun)</b> Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]		
Claimant's Insurer:	<b>Lonpac Insurance Bhd (HQ)</b> - Tel: +65 62507388		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 22/09/2020]		

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**SKV6419R (SNM20D203299/C02/TKL)  
[YN6416A]  
TP  
KUAN KOW KHIANG  
Aug 29 2020 9:00AM  
[TUNG SHUN PTE LTD]  
Cheng Hoe Motor Pte Ltd**

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		<b>Thumbnail</b> <b>Print</b>
1	29/08/20 14:42	<b>Accident Statement</b>		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	17/09/20 17:12	<b>Adjuster Immediate Advice</b>		Load HTM
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		<b>Thumbnail</b> <b>Print</b>
1	16/09/20 12:09	<b>Repairer Estimates</b>		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		<b>Thumbnail</b> <b>Print</b>
1	29/08/20 14:40	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
2	29/08/20 14:40	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
3	29/08/20 14:40	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
4	29/08/20 14:40	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
5	29/08/20 14:40	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
6	29/08/20 14:40	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
7	29/08/20 14:40	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
No	<b>Relabel/Reorder</b>	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	29/09/20 14:43	<b>General View</b>		Load PDF
2	29/09/20 14:44	<b>Reinspection Photo</b>		Load PDF

## Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		<b>Thumbnail</b> <b>Print</b>
1	29/08/20 14:42	<b>Accident Statement</b>		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		<b>Thumbnail</b> <b>Print</b>
1	29/08/20 14:40	<b>Accident Photo</b>		Load JPG <input checked="" type="checkbox"/>
2	29/08/20 14:40	<b>Accident Photo</b>		Load JPG <input checked="" type="checkbox"/>
3	29/08/20 14:40	<b>Accident Photo</b>		Load JPG <input checked="" type="checkbox"/>
4	29/08/20 14:40	<b>Accident Photo</b>		Load JPG <input checked="" type="checkbox"/>
5	29/08/20 14:40	<b>Accident Photo</b>		Load JPG <input checked="" type="checkbox"/>
6	29/08/20 14:40	<b>Accident Photo</b>		Load JPG <input checked="" type="checkbox"/>
7	29/08/20 14:40	<b>Accident Photo</b>		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		<b>Thumbnail</b> <b>Print</b>
1	29/08/20 14:38	<b>Sketch Plan</b>		Load JPG <input checked="" type="checkbox"/>
2	29/08/20 14:38	<b>Sketch Plan #2</b>		Load JPG <input checked="" type="checkbox"/>
3	29/08/20 14:39	<b>PR</b>		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
4	29/08/20 14:39	<b>PR</b>	Load JPG	<input checked="" type="checkbox"/>
5	29/08/20 14:39	<b>PR</b>	Load JPG	<input checked="" type="checkbox"/>
6	29/08/20 14:39	<b>Driving License</b>	Load JPG	<input checked="" type="checkbox"/>
7	29/08/20 14:39	<b>Driving License</b>	Load JPG	<input checked="" type="checkbox"/>
8	29/08/20 14:39	<b>Identification Card</b>	Load JPG	<input checked="" type="checkbox"/>
9	29/08/20 14:39	<b>Identification Card</b>	Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI20009741/KVD3S2**Date:** 01/10/2020REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30705019044

**Claimant Vehicle No :** SKV6419R **Insured Vehicle No :** YN6416A

Date of Loss: 29/08/2020 Nature of Claim: TP Claim No: SNM20D203299/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV6419R**

Make & Model: TOYOTA PRIUS C, 1.5 HYBRID CVT (A) Engine No: 1NZR300369

Reg. Date: 28/09/2015 (Man. Year: 2015) Chassis No: JTDKD3B3701101634

Colour: Red Odometer: 74258 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,907.00	1,822.00	85.00	4.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	1,130.00	130.00	10.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,167.00</b>	<b>2,952.00</b>	<b>215.00</b>	<b>6.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>(S\$)</b>	3,167.00	2,350.00	817.00	25.80
<b>+ GST 7.00/7.00% (S\$)</b>	221.69	164.50	57.19	25.80
<b>Nett Amount (S\$)</b>	<b>3,388.69</b>	<b>2,514.50</b>	<b>874.19</b>	<b>25.80</b>

INSPECTION

Date of Assignment: 11/09/2020 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 16/09/2020 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 01 Oct 2020)**Parts:** 144      TOYOTA PRIUS C 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKV6419R)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT RH FENDER	Bent	260.00 F	*260.00 F
2	1		*1 PC RH HEADLAMP	Cut	980.00 F	*980.00 F
3	1		*1 PC BONNET	Bent	290.00 F	*290.00 F
4	1		*1 PC FRT RH FENDER EMBLEM HYBRID	Necessary	50.00 F	*50.00 F
5	1		*1 PC FRT BUMPER	Deep Cut	185.00 F	*185.00 F
6	1		*1 PC FRT BUMPER LOGO	Necessary	45.00 F	*45.00 F
7	1		*6 PCS FRT BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
8	1		*1 PC FRT BUMPER LAMP	Serviceable	85.00 F	*- F

F=Franchise part.

<b>Total Parts (\$)</b>	<b>1,907.00</b>	<b>1,822.00</b>
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX FRT BUMPER,FOG LAMPS,CENTER LOWER GRILLE,FRT RH FENDER,GRILLE,HEADLAMP & REALIGN THE SAME	New	550.00	500.00
2	PUTTY & RESPRAY ON FRT BUMPER,BONNET,FRT RH FENDER	New	680.00	600.00
3	RUSTPROOFING	New	30.00	30.00
			<b>Gross Labour Cost (\$)</b>	<b>1,260.00</b>
				<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >