

FIRST AUTOWORKS

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 10/9/2020

Reference: SKN8259P
CHEVROLET /
CAPTIVA C140
Make: 2.4D FWD 6AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SKN8259P
CHASSIS NO.:KL1CA26UJEB040788
ENGINE NO.:LE9141270064

Name of insured :MONG KOK HUNG
Date of accident.:03/09/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Bonnet <i>Not m</i>	\$ 2,615.00
2	1	LHF Headlamp <i>3 new</i>	\$ 1,508.00
3	1	RHF Headlamp <i>3 new</i>	\$ 1,508.00
4	1	Front Number Plate Bracket <i>Repld</i>	\$ 83.00
5	1	Front Bumper - Upper <i>Repld Deformed</i>	\$ 1,662.00
6	1	Front Bumper - Lower <i>Repld</i>	\$ 780.00
7	20	Front Bumper Clips <i>new</i>	\$ 130.00
8	1	Front Bumper Emblem <i>new</i>	\$ 90.00
9	1	Front Bumper Upper Grille With Chrome <i>new</i>	\$ 713.00
10	1	Front Bumper Lower Grille with chrome <i>new</i>	\$ 942.00
11	1	Front Bumper Lower Moulding - Deflector, RH <i>3 new</i>	\$ 193.00
12	1	Front Bumper Lower Moulding - Deflector, LH <i>3 new</i>	\$ 119.00
13	1	Front Bumper Lower Silver Moulding - Skid Plate <i>new</i>	\$ 557.00
14	1	LHF Foglamp <i>2</i>	\$ 388.00
15	1	LHF Foglamp Cover with Chrome <i>3 new new</i>	\$ 318.00
16	1	RHF Foglamp	\$ 388.00
17	1	RHF Foglamp Cover with Chrome	\$ 318.00
18	1	LHF Bumper Bracket - Guide <i>3</i>	\$ 65.00
19	1	RHF Bumper Bracket - Guide <i>3</i>	\$ 65.00
20	1	Front Bumper Absorber - Upper <i>3</i>	\$ 323.00
21	1	Front Bumper Absorber - Lower <i>3</i>	\$ 171.00
22	1	Front Bumper Reinforcement Bar <i>new</i>	\$ 1,590.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

23	1	Tailgate	new	\$	2,860.00	+
24	1	Lettering "CAPTIVA LT"	new	\$	57.00	+
25	1	Lettering "CHEVROLET"	new	\$	56.00	+
26	1	Rear Windscreen	new	\$	932.00	+
27	1	Moulding, Rear Windscreen	new	\$	121.00	+
28	1	RHR Taillamp	new	\$	1,475.00	+
29	1	RHR Bumper Upper	new	\$	328.00	+
30	1	LHR Taillamp	new	\$	1,475.00	+
31	1	LHR Bumper Upper	new	\$	328.00	+
32	1	Rear Bumper Lower	new	\$	885.00	+
33	10	Rear Bumper Clips	new	\$	65.00	+
34	1	RHR Bumper Reflector - Fog Lamp	new	\$	662.00	+
35	1	LHR Bumper Reflector - Fog Lamp	new	\$	662.00	+
36	1	Rear Bumper Sill Plate(Silver)	new	\$	570.00	+
37	1	RHR Fender Protector	new	\$	176.00	+
38	1	LHR Fender Protector	new	\$	176.00	+
39	8	Fender Protector clips	new	\$	52.00	+
40	1	LHR Exhaust Pipe with muffler	new	\$	1,885.00	+
41	1	RHR Exhaust Pipe with muffler	new	\$	1,885.00	+
42	1	Tailgate Inner Trim - Lower	new	\$	325.00	+
43	1	Rear End Panel	new	\$	458.00	+
44	1	Rear End Panel Trim	new	\$	150.00	+
45	1	Rear Spare Tyre Panel Mat	new	\$	150.00	+
46	1	Rear Bumper reinforcement Bar	new	\$	566.00	+
47	1	Reverse Sensor - 1 set	new	\$	440.00	+

8384
7545.60

Parts Total: \$ 31,265.00
Less 10%: \$ 3,126.50
Total : \$ 28,138.50

Labour

Labour Description

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$	1,650.00	825
2	Carry out spray painting on accident affected area (\$450 per panel)	\$	1,800.00	900
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	30.00	✓
4	To refocus headlamp	\$	80.00	+

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$	2,750.00	1375
2	Carry out spray painting on accident affected area (\$450 per panel)	\$	2,250.00	1350
3	To conduct anti rust of under carriage tuff coat	\$	80.00	30
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	100.00	30
5	To remove and refix reverse sensor and conduct test	\$	80.00	50
6	To conduct transfer of parts from old tailgate to new tailgate	\$	80.00	+
7	To conduct water leakage test after repairs of vehicle	\$	80.00	+

4590

8	To remove and refix rear tail gate windscreen	\$ 120.00
---	---	-----------

Labour Total : \$ 9,100.00

Others

Other Description

<u>No.</u>	<u>Qty</u>	<u>Front portion</u>	<u>Price (SGD)</u>
1	1	Number plate with casement <i>centred</i>	\$ 45.00

Other Total: \$ 45.00

45.
Total: \$ 37,283.50
GST 7%: \$ 2,609.85
GRAND TOTAL: \$ 39,893.35

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Adviser
Ronnie Tan

Adrian Lj
P/P 10/09/20
07 Days.

VEHICLE NO:

SKN 8259P

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date: