#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20009758/GCD3E2

**Date:** 22/03/2021

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant Vehicle No: FBN9885G Insured Vehicle No: SHD4051K

Date of Loss: 24/08/2020 Nature of Claim: TP Claim No: MCT20080360

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBN9885G

Make & Model: YAMAHA CZD300A / XMAX300, 292cc Engine No: H336E0047454

Reg. Date: 17/01/2019 (Man. Year: 2018) Chassis No: MH3SH0840KK005684

Colour: Yellow Odometer: 54760 km

Engine Capacity: 292 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 120/70-15 Rear Tyre Size: 150/70-14
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,058.00	2,248.20	809.80	26.48
Miscellaneous Items		0.00	0.00	0.00	
Labour		550.00	400.00	150.00	27.27
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,608.00	2,648.20	959.80	26.60
	Approved Total (Overridden) (S\$)		2,100.00		
	Nett Amount (S\$)	3,608.00	2,100.00	1,508.00	41.80

**INSPECTION** 

Date of Assignment: 11/09/2020

Motoplex Pte Ltd (HQ)

Date Inspected: 14/09/2020 Inspected At: 10 KAKI BUKIT ROAD 2, # 01-24 FIRST EAST

CENTRE

Singapore 417868

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

#### Reference

Part Source: (Last Synchronised: 22 Mar 2021)

Parts: N/A YAMAHA CZD300A / XMAX300 292cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBN9885G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD ASSY	Cut	120.00 F	*120.00 FL
2	1		*MIRROR RH	Cut	48.00 F	*48.00 FL
3	1		*MIRROR BRACKET ASSY	Cut	38.00 F	*38.00 FL
4	1		*UPPER FRONT COWLING B74-H2129-00 ASSY	Cut	84.00 F	*84.00 FL
5	1		*LOWER FRONT COWLING B74-F2865-00 ASSY	Cut	120.00 F	*120.00 FL
6	1		*WINDSCREEN	Cracked	240.00 F	*240.00 FL
7	1		*EXHAUST MUFFLER	Cut	680.00 F	*680.00 FL
8	1		*EXHAUST MUFFLER COVER	Cut	68.00 F	*68.00 FL
9	1		*BOX BRACKET	Cut	180.00 F	*180.00 FL
10	1		*TAIL COVER RH B74-F1741-00	Cut	68.00 F	*68.00 FL
11	1		*FLOOR BOARD RH	Cut	58.00 F	*58.00 FL
12	1		*BRAKE LEVER RH	Cut	28.00 F	*28.00 FL
13	1		*FRONT AXLE SLIDER ASSY	Bent	58.00 F	*58.00 FL
14	1		*FRONT SIDE COVER RH B74-F835K-00	Cut	70.00 F	*70.00 FL
15	1		*LOWER SIDE COVER RH B74-F171M-00	Cut	44.00 F	*44.00 FL
16	1		*TAIL COVER LOGO B74-F173B-00	Necessary	40.00 F	*40.00 FL
17	1		*FRONT RIM	Bent	400.00 F	*400.00 FL
18	2		*FRONT FORK	Repair	560.00 F	*- FL
19	1		*REAR FOOTREST	Broken	28.00 F	*28.00 FL
20	1		*REAR FOOTREST BRACKET	Broken	48.00 F	*48.00 FL
21	1		*UNDER COVER	Cut	78.00 F	*78.00 FL
F=Fra	anchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	3,058.00	2,498.00
	- List Item Discount on L Items 0.00/10.00% (S\$)					249.80
				Total Parts (S\$)	3,058.00	2,248.20
				_		

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
<u>Lab</u>	our Items				
1	FRONT RIM PAINT	New	100.00	100.00	
2	LABOUR	New	450.00	300.00	
		Gross Labour Cost (S\$)	550.00	400.00	
Report was unsubmitted during this print-out.					

< END OF ESTIMATES >