

FBN 9885G XMax 300

Date

No

Front mudguard assy \$120 / Cnt

Mirror RH \$48 Cnt

Mirror Bracket assy / Cnt \$38

upper Front cowling B74-H2129-00 assy \$44 / Cnt

lower Front cowling B74-F2865-00 assy \$120 / Cnt

windscreen \$240 Cnt

Exhaust muffler \$680 Cnt

Exhaust muffler cover \$68 Cnt

Box Bracket \$180 Cnt

tail cover RH B74-F1741-00 \$68 Cnt

Floor board RH \$58 / Cnt

Brake lever RH \$28 / Cnt

Front side slider assy \$58 / Cnt

Front side cover RH B74-F835K-00 \$70 / Cnt

Lower side cover RH B74-F171M-00 \$44 / Cnt

tail cover logo B74-F173B-00 \$40 / MC

Front Rim \$400 / Cnt

Front Fork ~~\$320x2~~ \$280x2 \$560 repair X

Rear Footrest \$28 / Cnt

Rear Footrest Bracket \$48 / Cnt

under cover \$78 / Cnt

Front Rim paint \$100 /

Labour \$450 300

2498

-10%: 2248.2

2648.2

-20%: 2100

Em-Q: up.

3 Days.

Insurance repair.

After repair photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company