

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC4/11120009760/46a3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA8808L

at Workshop m/s

Trans Eurler

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£80

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

131

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 49331

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLA8808L

Yr Regn:

*11/18*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA

Make:

Mazda 6

C.C

1998

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

52190

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*JM66L1071J0133072*Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

29/8/20

D.O.I.

11/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or*Rear*

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

*Rep 9500**18/2/21 P1/P2 4379.20 confirmed with Jen*

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

11 Sept 2020

not Authorized

11/9/20
Take photo before painting
Holidays

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Teo Beng Chai ADDRESS : 88 Sea Breeze Avenue Singapore 487587 TEL : 90063399		WIP : 34944 EXCESS : DATE: 31-Aug-20	
VEH NO :	SLA8808L	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1071J0133072	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 6	DATE REG.:	31-Jan-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJS1-50-221ABB	DO/Re	\$ 1,266.60
2	BRACKET CENTER	1	MKD53-50-251	17	\$ 5.40
3	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	rec	\$ 10.80
4	FASTENER, REAR BUMPER	6	MB45A-56-146A	rec	\$ 18.00
5	GROMMET, REAR BUMPER	2	MH260-50-841	rec	\$ 6.00
6	CLIP, REAR BUMPER	4	MC274-50-133	rec	\$ 14.80
8	TAPE PROTECTOR, REAR BUMPER	4	MGS1D-50-EM1A	rec	\$ 34.40
9	RETAINER CENTER LHS, SENSOR	1	MKD45-67-UC5A62	17	\$ 18.20
10	SENSOR CENTER LHS, ULTRASONIC	1	MGMK6-67-UC1 62	17	\$ 180.90
11	BOOTLID	1	MGJY0-52-61X	17	\$ 1,115.00
12	GROMMET, BOOTLID	2	MGA7B-51-146	17	\$ 6.60
13	GASKET LHS, TAILLAMP	1	MGJA1-51-163	rec	\$ 27.70
14	GASKET RHS, TAILLAMP	1	MGJA1-51-153	rec	\$ 27.70
15	GASKET LHS, BOOTLID	1	MG45F-51-3J8A	17	\$ 49.20
16	GASKET RHS, BOOTLID	1	MG45F-51-3H8A	17	\$ 49.20
17	ANTENNA	1	MKD47-67-6NXA	17	\$ 111.10
18	CLIP, ANTENNA	1	MKD45-67-6NYA	17	\$ 2.70
19	REAR REINFORCEMENT	1	MGHK1-50-260	DO	\$ 538.30
20	TOWING COVER LHS	1	MG4YL-50-EL1 62	mis	\$ 24.90
TOTAL PARTS					\$ 3,507.50
TOTAL PARTS COST					\$ 3,507.50
Labour Description					
1	MZ-BR-REAR03	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND BOOT LID.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			660 \$ 2,310.00

2	MZ-SP-SREAR3	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND BOOT LID. 630	1260	\$ 2,205.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	200	\$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	~1x	\$ 330.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	~1x	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
8	MZ-BR-SUNDRI	SUNDRIES. net 20	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 6,125.00
TOTAL PARTS	\$ -	\$ 3,507.50
TOTAL	\$ -	\$ 9,632.50
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____