



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteid@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Not Authorised

ATTN: Motor Claim Department

11 Sep @ 4950ph

Your Ref No:

Accy After Paint

Claim Type: Third Party

Accident Date: 10/09/2020

5 days

TP Veh Reg No: SBQ2899Y

Estimate No: ES20000085

Date: 12 Sep 2020

Policy No:

GBH3188G

Veh Reg No:

TOYOTA HIACE VAN

Make/Model:

TURBO 5DR MT

Chassis No: JTFHT02PS00242293

Engine No: 1KD2796523

Reg. Date: 24/04/2018

Estimate Repair Cost to Vehicle No :GBH3188G

Description	U/Price	Quantity	List Price	Amount
			SS	SS

1	REVERSE SENSORS	1 SET	280.00	280.00
2	REAR WINDSCREEN SEALANT	1 PC	60.00	60.00
3	REAR FLOOR WOODEN PLANK	1 PC	450.00	450.00
4	REVERSE CAMERA	1 PC	350.00	350.00
5	SPEED LIMIT STICKER 70KM/H	1 PC	20.00	20.00
				1,160.00

Spare Parts

6	REAR BUMPER	1 PC	625.50	625.50
7	REAR BUMPER BRACKET - LH	1 PC	32.20	32.20
8	REAR BUMPER BRACKET - RH	1 PC	32.20	32.20
9	REAR BUMPER SIDE RETAINER - LH	1 PC	48.40	48.40
10	REAR BUMPER SIDE RETAINER - RH	1 PC	48.40	48.40
11	REAR BUMPER CLIPS	1 SET	60.00	60.00
12	REAR END PANEL	1 PC	585.00	585.00
13	REAR END INNER PANEL	1 PC	543.50	543.50
14	REAR END PANEL TOP PLATE	1 PC	175.10	175.10
15	TAIL LAMP RH	1 PC	295.20	295.20
16	REAR TAILLAMP LOWER GARNISH - LH	1 PC	95.60	95.60
17	REAR TAILLAMP LOWER GARNISH - RH	1 PC	95.60	95.60
18	TAIL LAMP LH	1 PC	295.20	295.20
19	REAR TAILLAMP PANEL - LH	1 PC	242.00	242.00
20	REAR FLOOR PANEL	1 PC	1,455.30	1,455.30
21	REAR TAILGATE	1 PC	1,855.60	1,855.60
22	REAR TAILGATE ABSORBER - LH	1 PC	287.40	287.40
23	REAR TAILGATE ABSORBER - RH	1 PC	287.40	287.40
24	REAR TAILGATE WEATHERSTRIP	1 PC	155.60	155.60
25	REAR TAILGATE HINGE - LH	1 PC	110.00	110.00
26	REAR TAILGATE HINGE - RH	1 PC	110.00	110.00
27	REAR TAILGATE OUTER GARNISH	1 PC	225.30	225.30
28	REAR TAILGATE OUTER HANDLE	1 PC	98.20	98.20
29	REAR TAILGATE INNER TRIMBOARD	1 PC	318.30	318.30
30	REAR TAILGATE EMBLEM 'LOGO'	1 PC	71.40	71.40
31	REAR TAILGATE HINGE STICKER	1 PC	56.50	56.50
32	REAR TAILGATE LOCK	1 PC	362.30	362.30
33	REAR TAILGATE TOP LOCK	1 PC	193.70	193.70
34	REAR TAILGATE TOP LOCK COVER	1 PC	25.00	25.00

251



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteid@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: Sompoo Insurance Singapore Pte Ltd
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/09/2020
TP Veh Reg No: SBQ2899Y

Estimate No: ES2000085
Date: 12 Sep 2020
Policy No:
Veh Reg No: GBH3188G
Make/Model: TOYOTA HIACE VAN
TURBO 5DR MT
Chassis No: JTFHT02P500242293
Engine No: 1KD2796523
Reg. Date: 24/04/2018

Estimate Repair Cost to Vehicle No: GBH3188G

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 REAR NUMBER PLATE LAMP - LH	113.20	1 PC	113.20	X
36 REAR NUMBER PLATE LAMP - RH	113.20	1 PC	113.20	X
37 THIRD BRAKE LAMP	198.50	1 PC	198.50	X
38 SPARE WHEEL CARRIER	328.50	1 PC	328.50	X
			9,539.30	9,539.30
Labour				
39 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	700l
40 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	800l
41 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	60l
42 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	250.00	1 JOB	250.00	120l
43 TO REMOVE/TRANSFER TAILGATE MECHANISMS.	150.00	1 JOB	150.00	60l
44 TO CHECK WIRING FUNCTIONS.	120.00	1 JOB	120.00	20l
			4,320.00	4,320.00
Total			SS 15,019.30	
Add GST @ 7%				1,051.35
Total Amount Payable				SS 16,070.65

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND SEVENTY AND CENTS SIXTY FIVE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE