

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: HLW00096
Date calculated: 16/09/2020 10:59 AM

Full Report
Registration: SKW451E OD
Printed: 16/09/2020 10:59 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	03/09/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL RU1/5
Sub Model:	EX
Model Sheet Number:	35 VE 06
Registration:	SKW451E OD
VIN number:	RU11101828
Odometer:	79674

Model Specs

FROM MODEL 2018	AUTO AIR CON	1496CCM 97KW	TWO COAT PEARL/MICA
-----------------	--------------	--------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 45.00 SGD/h

Code	Description	WU	Price SGD
831120	R + R WINDSCREEN INCLUDES: FRT AIR GRILLE, WIPER ARM AND REQUIRED TRIMS REMOVE AND REFIT	26.0	117.00
1322	INN FIREWALL INSUL CHECK		
4300	HEATER BLOWER MOTOR CHECK		
4331	INSTRUMENT PANEL CHECK		
4411	HEATER BLOWER CHECK		
4412	BLOWER MOTOR CHECK		
4416	AIR VENT DUCTING CHECK		
4494	POLLEN FILTER CHECK		
4873	FRONT FLOOR CARPET CHECK		
4941	L/UPP A-PILLAR TRIM CHECK		
1000	BBC UNIT CHECK		
1001	MODULE SET, EDLC CHECK		
1002	HARNESS,L CABIN WIRE CHECK		
1003	HARNESS INSTR WIRE CHECK		
1004	LWR WINDSCREEN CHECK		
1005	DISMANTLE,R & REFIT CHECK		
1006	DISMANTLE,R & REFIT CHECK		
1007	DISMANTLE,R & REFIT CHECK		
1009	IN-CAR CLEANING CHECK		
1010	CLEANING CHECK		
1013	AIR CON COOLANT CHECK		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		2.60	26.0
Total of Labour			117.00

Spare Parts

prices as at 2015-06-01/01				Price SGD
Code	Description	Part Number	Part Source	
1413	FRT SCREEN MNTG KIT	91568TF0003	Original	30.00
1415	L/WINDSCREEN MLDG	73125T7A003	Original	60.00
1423	LWR FRT SCREEN SEAL	77466SV4000	Original	20.00
1432	UPP WINDSCREEN MLDG	73150T7A003	Original	40.00
1401	WINDSCREEN	73111T7YY01	Original	1,430.00
1411	WINDSCREEN BOND KIT KNGKWI2			0.00
Savings				0.00
Subtotal				1,580.00
Addition(+10.00%)				158.00
Total				1,738.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1008	DISMANTLE,R & REFIT WINDSCREEN	400.00*
1011	CHECK WIRING	200.00*
1012	SILICON - WINDSCREEN	60.00*
Total Extras		660.00

Final Calculation

	SGD	SGD
Parts	1,580.00	
Addition(+10.00%)	158.00	
Total Parts		1,738.00
Labour Time Base 10 WU/h		
Total 26.0 WU X 45.00 SGD/h	117.00	
Total of Labour		117.00
Total Of Extras		660.00
Repair Cost Excludes GST		2,515.00
GST (+7.00%)		176.05
Repair Cost Included GST		2,691.05

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.