



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2015 HONDA VEZEL 1.5 (SKW451E)
Date of Loss	3 September 2020
Time of Loss	17.45
Loss Description	SKW451E (INSD) - FIRE
Comment	

Workshop Details

Total Rebate Amount	36135
Nett Loss Amount	\$21,865.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion	20



*

<<

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#	SKW451E	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>15/10/2015</div> <div></div>
Mileage	<div></div>	Age of Vehicle	4

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2015	<div>2015</div>
Make	HONDA	<div>HONDA</div>
Model	VEZEL 1.5	<div>VEZEL 1.5X A</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	NATARAJAN SELVAKUMAR	<div></div>
Date of Birth	7 July 1978	<div>dd/mm/yy</div> <div></div>
Age	42	

Type	POLICY	ASSESSMENT INFORMATION
CATEGORY	INFORMATION	
Type of Paint		
Chassis No	RU11101828	RU11101828
Engine No	L15B4021831	L15B4021831
Engine Capacity		1496
Sum Insured	0	0
Market Value	0	58000

CATEGORY	ENROLLMENT	ENROLLMENT INFORMATION
Occupation	Enrollment	
Education Qualification	Other	
Driving Experience	5	
Driver License #		
License Type		
License Issue Date		dd/mm/yy
License Expiration Date		dd/mm/yy
Address	BLK 509 WOODLANDS DRIVE 14, #10-07, 730509, Singapore	
Address type	Residential	

CATEGORY		FNOL INFORMATION	POST SURVEY INFORMATION
Gender		Male	<div>▼</div>
Marital status		Married	<div>▼</div>
Identification #		S7865862B	<div></div>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

15/09/2020



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1000

Young/Inexperienced/Un
named Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Poor



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Poor



Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/60R16

Front left side

MICHELIN7mm

Front right side

MICHELIN7mm

Rear Tyre Size

215/60R16

Rear left side

YOKOHAMA7mm

Rear right side

YOKOHAMA7mm

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary















Parts





















Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		HEATER BLOWER MOTOR (WCP) (10%)	Damaged	0	302.5	No					302.5	Reviewing	
<input type="checkbox"/>		0	1		HEATER BLOWER (WCP) (10%)	Damaged	0	401.5	No					401.5	Reviewing	
<input type="checkbox"/>		0	1		BLOWER MOTOR (WCP) (10%)	Necessary	0	462	No					462	Reviewing	
<input type="checkbox"/>		0	1		POLLEN FILTER (WCP) (10%)	Damaged	0	82.5	No					82.5	Reviewing	
<input type="checkbox"/>		0	1		L/UPP A-PILLAR TRIM (WCP) (10%)	Damaged	0	71.5	No					71.5	Reviewing	
<input type="checkbox"/>		0	1		BBC UNIT (WCP) (10%)	Damaged	0	1215.5	No					1215.5	Reviewing	
<input type="checkbox"/>		0	1		HARNESS, L CABIN WIRE (WCP) (10%)	Damaged	0	990	No					990	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		HARNESS INSTR WIRE (WCP) (10%)	Damaged	0	1402.5	No					1402.5	Reviewing	
<input type="checkbox"/>		0	1		LWR WINDSCREEN (WCP) (10%)	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		INSULATOR, DASHBOARD (WCP) (10%)	Damaged	0	902	No					902	Reviewing	
<input type="checkbox"/>		0	1		PANEL COMP, INSTRUMEN (WCP) (10%)	Damaged	0	786.5	No					786.5	Reviewing	
<input type="checkbox"/>		0	1		CARPET ASSY, FLOOR (WCP) (10%)	Damaged	0	2574	No					2574	Reviewing	
<input type="checkbox"/>		0	1		WINDSCREEN (WCP) (10%)	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		FRT SCREEN MNTG KIT (WCP) (10%)	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		L/WINDSCREEN MLDG (WCP) (10%)	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		LWR FRT SCREEN SEAL (WCP) (10%)	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		UPP WINDSCREEN MLDG (WCP) (10%)	Serviceable	0	0	No					0	Deny	

Labour

















Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------	--------

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		DISMANTLE, R & REFIT SEAT	0	100	0	0	Reviewing		
<input type="checkbox"/>		0		DISMANTLE, R & REFIT HARNESS	0	300	0	0	Reviewing		
<input type="checkbox"/>		0		IN-CAR CLEANING	0	200	0	0	Reviewing		
<input type="checkbox"/>		0		CHECK WIRING	0	100	0	0	Reviewing		
<input type="checkbox"/>		0		316.0 WU X 45.00 SGD/H	0	1017	0	0	Reviewing		
<input type="checkbox"/>		0		LABOUR COST 19.0 WU X 45.00 SGD/H	0	85.5	0	0	Reviewing		
<input type="checkbox"/>		0		MATERIAL COST	0	42	0	0	Reviewing		
<input type="checkbox"/>		0		TOWING FEE	0	60	0	0	Reviewing		



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 21 DAYS	Reviewing		0		
<input type="checkbox"/>		0	SILICON WINDSCREEN	Reviewing		60	NECESSARY	
<input type="checkbox"/>		0	AIR CON COOLANT	Reviewing		50	NECESSARY	



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$10,205.00

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$9,190.50
Labour	\$0.00	\$1,904.50
Miscellaneous	\$0.00	\$110.00
Excess		-\$1,000.00

Submit for Review