



1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 12 September 2020

geg.: Lkk - Marcus

S/No	Quantity	Description	Amount
		<u>NETT ITEMS</u>	
01	1 pc	rear bumper <i>D/S</i>	\$ 650.40
02	8 ps	rear bumper clips @ \$4.50 <i>neu</i>	\$ 36.00
03	2 ps	rear bumper reflector @ \$65.00 <i>n/s c/o</i>	\$ 130.00
04	1 pc	rear bumper tow cover <i>11</i>	\$ 45.00
05	2 ps	rear bumper side retainer @ \$35.20 <i>11</i>	\$ 70.40
06	1 pc	rear bumper foam <i>for</i>	\$ 133.80
07	1 pc	rear end panel outer <i>body</i>	\$ 246.20
08	1 pc	rear end panel inner <i>body</i>	\$ 320.00
09	1 pc	rear end panel garnish <i>c/o</i>	\$ 84.00
10	6 ps	rear end panel garnish clips @ \$2.50 <i>neu</i>	\$ 15.00
11	1 pc	o/s rear tailgate <i>body</i>	\$ 1,053.70
12	1 pc	o/s rear tailgate lock top <i>11</i>	\$ 90.50
13	1 pc	o/s rear tailgate lock bottom <i>7m/1gm</i>	\$ 90.50
14	1 pc	o/s rear tailgate latch top <i>11</i>	\$ 31.80
15	1 pc	o/s rear tailgate latch bottom <i>11</i>	\$ 31.80
16	1 pc	o/s rear tailgate hinge top <i>11</i>	\$ 99.60
17	1 pc	o/s rear tailgate hinge bottom <i>11</i>	\$ 99.60
18	1 pc	o/s rear tailgate weatherstrip <i>7m</i>	\$ 82.60
19	1 pc	n/s rear tailgate <i>body</i>	\$ 1,404.90
20	1 pc	n/s rear tailgate lock top <i>11</i>	\$ 90.50
21	1 pc	n/s rear tailgate lock bottom <i>7m/1gm</i>	\$ 90.50
22	1 pc	n/s rear tailgate latch top <i>11</i>	\$ 31.80
23	1 pc	n/s rear tailgate latch bottom <i>11</i>	\$ 31.80
24	1 pc	n/s rear tailgate hinge top <i>11</i>	\$ 99.60
25	1 pc	n/s rear tailgate hinge bottom <i>11</i>	\$ 99.60
26	1 pc	n/s rear tailgate checker/arrestor <i>11</i>	\$ 69.00
27	1 pc	n/s rear tailgate weatherstrip <i>NT</i>	\$ 84.90
28	1 pc	rear rear tailgate inner weatherstrip <i>7m</i>	\$ 77.10
29	2 ps	tail lamp @ \$257.30 <i>11</i>	\$ 514.60
30	1 pc	spare tyre holder <i>11</i>	\$ 298.20
31	<i>2 ps/at</i>	rear bumper parking sensor @ \$295.50 <i>sholeb</i>	\$ 591.00
32	1 pc	rear tailgate Nissan emblem <i>neu</i>	\$ 64.60
33	1 pc	rear tailgate NV200 emblem <i>neu</i>	\$ 163.50
34	1 pc	rear tailgate DCI emblem <i>NT</i>	\$ 64.60
35	2 ps	rear licence plate lamp @ \$62.00 <i>11</i>	\$ 124.00
			\$ 7,211.10
		Less 10 %	\$ 721.11
			\$ 6,489.99



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SH9179S
Date of Accident : 10 September 2020

Messrs Asia Pacz Pte Ltd

Date : 12 September 2020

Estimate To Repair GBD6161J - NISSAN NV200
Chassis No : VSKYBAM20Z0083649

S/No	Quantity	Description	Amount
SPECIAL NETT ITEMS			
36	1 pc	rear tailgate 70KM/H sticker <i>neu</i>	\$ 20.00 <i>10</i>
37	1 pc	rear licence plate <i>11</i>	\$ 50.00 <i>X</i>
38	2 ps	rear windscreen glass sealant @ \$50.00 <i>neu</i>	\$ 100.00 <i>70</i>
39	1 set	rear tailgate company advertisement wording sticker <i>neu</i>	\$ 350.00 <i>300</i>
			\$ 520.00
LABOUR & MISC. CHARGES			
01		To transfer of both tailgate fittings, fixture and perform waterseepage test.	\$ 250.00 <i>100</i>
02		To remove and refit both rear windscreen glass.	\$ 240.00 <i>200</i>
03		To reinstall of rear bumper parking sensor.	\$ 100.00 <i>40</i>
04		To rust-proofing of the affected areas.	\$ 350.00 <i>100</i>
05		To check electrical lighting concerned.	\$ 80.00 <i>20</i>
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,400.00 <i>900</i>
07		Putty and spray painting of the affected portion.	\$ 1,400.00 <i>700</i>
			\$ 3,820.00
		Total	\$ 10,829.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SH9179S
Date of Accident : 10 September 2020

Messrs Asia Pacz Pte Ltd

Date : 15 September 2020

Supplementary To Repair GBD6161J - NISSAN NV200
Chassis No : VSKYBAM20Z0083649

S/No	Quantity	Description	Amount
01	1 pc	<u>SPECIAL NETT ITEMS</u> rear floor wooden board 012	\$ 400.00
			\$ 400.00
		Total	\$ 400.00

380