

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/FCR20009791/UK93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGV 1969A

at Workshop m/s

Rf.

of

Insured:

SHIA 8770H

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 4 3/4.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

204H

Vehicle: IN / OUT

Date:

Person Contacted:

007 8500

Veh No:

SGV 1969A

Yr Regn:

6,15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mazda 3

5P

c.c

1496

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

69967

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM 6BM42A8G 030 P805

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Bordered / Jammed / Leaked / Burnt or

Brake:

Bordered / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/9/20

D.O.I.

14/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 36003 have video at folder

29/9/20 4/5 @ 1300 Confirmed with Alan.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48, AUTO BAY
SINGAPORE 417883

Umm. khaadone

Not Authorized
Lulu
14/9/20
2/5 1300/
245.

VEHICLE No: SGV 1969A

1PC	REAR BUMPER	Deep Cut	\$1,074.00 ✓
1SET	REAR BUMPER CLIPS	NA	\$50.00 ✓
1PC	REAR FENDER N/S	R	\$945.20 X
			\$2,069.20

20%

TO CHECK WIRING	\$50.00
TO REMOVE & REFIX REAR REVERSE SENSOR	\$80.00 } 50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$100.00 60
LABOUR FOR PAEL BEATING & REPLACED PARTS	\$480.00 220
TO PUTTY & SPRAY PAINTING	\$600.00 400
TOTAL	\$3,379.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 1124
208
P- 899.20
L- 730
1629.2
202
1303