

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20009793/GES3Q2**Date:** 11/01/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900083332   |
| <b>Claimant Vehicle No :</b> | FBH454H                              | <b>Insured Vehicle No :</b> | SMK7231S     |
| Date of Loss:                | 28/08/2020                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 0224365963SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>FBH454H</b>                    | Engine No:  | SK40A1000152      |
| Make & Model:               | KYMCO DOWNTOWN 200l, 199cc        | Chassis No: | RFBSK40AEC1000137 |
| Reg. Date:                  | 22/02/2013 (Man. Year: 2012)      | Odometer:   | 35500 km          |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 199 cc                            |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 120/80-14     | Rear Tyre Size:  | 150/70-13     |
| Front Left Side:  | Michelin 4 mm | Rear Left Side:  | Michelin 4 mm |
| Front Right Side: | 0 mm          | Rear Right Side: | 0 mm          |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 3,444.00          | 2,543.20          | 900.80            | 26.16         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 530.00            | 400.00            | 130.00            | 24.53         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>3,974.00</b>   | <b>2,943.20</b>   | <b>1,030.80</b>   | <b>25.94</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>2,650.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 3,974.00          | 2,650.00          | 1,324.00          | 33.32         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 278.18            | 185.50            | 92.68             | 33.32         |
| <b>Nett Amount (S\$)</b>                        | <b>4,252.18</b>   | <b>2,835.50</b>   | <b>1,416.68</b>   | <b>33.32</b>  |
| <b>+ Loss of Use (3.0 x S\$20.00/day) (S\$)</b> |                   | 60.00             |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>2,902.95</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>2,900.00</b>   |                   |               |

INSPECTION

|                             |            |               |                                                                                   |
|-----------------------------|------------|---------------|-----------------------------------------------------------------------------------|
| Date of Assignment:         | 14/09/2020 |               |                                                                                   |
| Date Inspected:             | 14/09/2020 | Inspected At: | Motor Sport Pte Ltd - Ubi (HQ)<br>BLK 3007 UBI ROAD 1 #01-446<br>Singapore 408701 |
| Estimated Period of Repair: | 3.0 days   |               |                                                                                   |

**Adjuster:** XING GUO QIANG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|---------------|------------|------------|
| 1   | 1   |          | *SCREEN                         | Cracked       | 263.00 F   | *263.00 FL |
| 2   | 1   |          | *FRONT NUMBER PLATE             | Necessary     | 12.00 F    | *12.00 FL  |
| 3   | 1   |          | *HANDLE BAR                     | Bent          | 153.00 F   | *153.00 FL |
| 4   | 1   |          | *HANDLE CENTER COVER            | Missing       | 57.00 F    | *57.00 FL  |
| 5   | 1   |          | *RH BRAKE LEVER                 | Cut           | 88.00 F    | *88.00 FL  |
| 6   | 1   |          | *RH BAR END                     | Cut           | 15.00 F    | *15.00 FL  |
| 7   | 1   |          | *METER COVER                    | Cut           | 36.00 F    | *36.00 FL  |
| 8   | 1   |          | *FRONT COVER                    | Cut           | 245.00 F   | *245.00 FL |
| 9   | 1   |          | *FRONT COVER LH GRILL           | Cut           | 23.00 F    | *23.00 FL  |
| 10  | 1   |          | *FRONT COVER RH GRILL           | Cut           | 23.00 F    | *23.00 FL  |
| 11  | 1   |          | *HEADLAMP BRACKET               | Not Necessary | 115.00 F   | *- FL      |
| 12  | 1   |          | *LH HEADLAMP COMPLETE           | Cracked       | 437.00 F   | *437.00 FL |
| 13  | 1   |          | *LEGSHIELD                      | Cut           | 94.00 F    | *94.00 FL  |
| 14  | 1   |          | *FRONT FENDER                   | Repair        | 112.00 F   | *- FL      |
| 15  | 1   |          | *LH SIDE SKIRT                  | Cracked       | 128.00 F   | *128.00 FL |
| 16  | 1   |          | *LIT LH REAR SIDE SKIRT         | Cut           | 83.00 F    | *83.00 FL  |
| 17  | 1   |          | *LH FRONT ANTI FLOOR SKIP PLATE | Bent          | 35.00 F    | *35.00 FL  |
| 18  | 1   |          | *LH FOOTPEG                     | Cut           | 35.00 F    | *35.00 FL  |
| 19  | 1   |          | *LH CENTER COVER (FUEL TANK)    | Cut           | 41.00 F    | *41.00 FL  |
| 20  | 1   |          | *LH SIDE COVER                  | Cut           | 213.00 F   | *213.00 FL |
| 21  | 1   |          | *LH SIDE COVER EMBLEM           | Necessary     | 35.00 F    | *35.00 FL  |
| 22  | 1   |          | *AIR FILTER COVER               | Scratched     | 41.00 F    | *41.00 FL  |
| 23  | 1   |          | *LH ENGINE COVER                | Cut           | 115.00 F   | *115.00 FL |
| 24  | 1   |          | *SIDE STAND                     | Not Necessary | 24.00 F    | *- FL      |
| 25  | 1   |          | *MAIN STAND                     | Not Necessary | 82.00 F    | *- FL      |
| 26  | 1   |          | *RH SIDE COVER                  | Repair        | 213.00 F   | *- FL      |
| 27  | 1   |          | *RH SIDE COVER EMBLEM           | Necessary     | 35.00 F    | *35.00 FL  |
| 28  | 1   |          | *RH SIDE SKIRT                  | Cut           | 128.00 F   | *128.00 FL |
| 29  | 1   |          | *RH SIDE SKIRT REAR             | Cut           | 83.00 F    | *83.00 FL  |
| 30  | 1   |          | *EXHAUST COVER                  | Cut           | 106.00 F   | *106.00 FL |
| 31  | 8   |          | *EXHAUST CARBON SEAL            | Necessary     | 24.00 F    | *24.00 FL  |
| 32  | 1   |          | *TOP BOX                        | Cut           | 350.00 FS  | *250.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>3,444.00</b> | <b>2,798.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | 0.00            | 254.80          |
| <b>Total Parts (\$\$)</b>                                 | <b>3,444.00</b> | <b>2,543.20</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars    | Lab.Type | Repairer's    | Amount        |
|--------------------------------|----------------|----------|---------------|---------------|
| <b>Labour Items</b>            |                |          |               |               |
| 1                              | SPRAY PAINTING | New      | 280.00        | 200.00        |
| 2                              | LABOR CHARGE   | New      | 250.00        | 200.00        |
| <b>Gross Labour Cost (S\$)</b> |                |          | <b>530.00</b> | <b>400.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >