



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

14/09/2020

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP III
Jasper.

Accident date: 14/09/2020

Estimated repair cost for vehicle no: SMN4047L TOYOTA LEXUS IS300H CVT 14'

CHASSIS: JTHBH5D2605007031

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Repair</i>		\$2,452.25+
2	2	Front Bonnet Hinge <i>new</i>	\$171.85	\$343.70+
3	1	Front Bonnet Lock <i>new</i>		\$574.85+
4	1	Front Bonnet Insulator <i>new</i>		\$374.45+
5	8	Front Bonnet Insulator Clip <i>new</i>	\$6.50	\$52.00+
6	2	Front Bonnet Inner Side Rubber <i>new</i>	\$171.40	\$342.80+
7	2	Front Bonnet Inner Centre Rubber <i>new</i>	\$182.25	\$364.50+
8	2	Front Head Lamp <i>cracked</i>	\$2,350.45	\$4,700.90 ✓
9	2	Front Head Lamp Lower Bracket <i>cracked</i>	\$171.55	\$343.10 ✓
10	1	Front Bumper <i>delivered</i>		\$978.10 ✓
11	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
12	1	Front Bumper Inner Sponge <i>cracked</i>		\$182.50 ✓
13	1	Front Bumper Top Rubber <i>new</i>		\$165.60+
14	2	Front Bumper Side Retainer <i>new</i>	\$177.00	\$354.00 202
15	1	Front Bumper Number Plate <i>Best</i>		\$50.00 ✓
16	1	Front Bumper Centre Lower Garnish <i>cracked</i>		\$372.44 -
17	2	Front Bumper Centre Lower Garnish Sensor <i>new</i>		\$380.00+
18	2	Front Bumper Parking Sensor <i>Dayld</i>		\$380.00 ✓
19	2	Front Bumper Lamp <i>RT crkcd</i>	\$1,248.50	\$2,497.00 685
20	1	Front Bumper Reinforcement <i>Best</i>		\$581.90 ✓
21	2	Front Bumper Reinforcement Top Cover <i>delivered</i>	\$181.10	\$362.20 181/0
22	4	Front Bumper Reinforcement Top Cover Clip <i>new</i>	\$6.50	\$26.00 ✓
23	2	Front Bumper Nozzle <i>new</i>	\$571.48	\$1,142.95+
24	1	Front Bumper Towing Cover <i>?</i>		\$121.10+
25	2	Front Bumper Fog Lamp <i>new</i>	\$581.90	\$1,163.80+
26	2	Front Bumper Fog Lamp Cover <i>new</i>	\$377.10	\$754.20+
27	1	Front Grille <i>cracked</i>		\$671.45 ✓

28	1	Front Grille Center Garnish	new		\$258.69	X
29	1	Front Grille Chrome	cracked		\$581.90	✓
30	8	Front Grille Clip	new	\$6.50	\$52.00	20
31	1	Front Support Panel	new		\$1,712.40	X
32	1	Front Support Panel Top Cover	horn		\$305.45	✓
33	10	Front Support Panel Top Cover Clip	new	\$6.50	\$65.00	20
34	2	Front Horn	new	\$271.75	\$543.50	X
35	1	Front Air-Con Condenser	new		\$1,218.10	X
36	1	Front Air-Con Condenser Fan Motor Assy	new		\$972.85	X
37	1	Front Radiator	new		\$1,715.50	X
38	1	Front Radiator Fan Motor Assy	new		\$971.80	X
39	1	Rear Boot Lid	cracked		\$972.00	✓
40	2	Rear Boot Lid Hinge	new	\$174.25	\$348.50	X
41	1	Rear Boot Lid Emblem Logo	2		\$61.10	✓
42	1	Rear Boot Lid IS300H Logo	new		\$63.28	✓
43	1	Rear Boot Lid Lexus Logo			\$53.20	✓
44	2	Rear Boot Lid Side Reflector	new	\$597.20	\$1,194.40	X
45	1	Rear Boot Lid Reverse Camera	new		\$680.00	X
46	1	Rear Boot Lid Number Plate	new		\$50.00	X
47	2	Rear Boot Lid Number Plate Lamp	new	\$61.10	\$122.20	X
48	1	Rear Boot Lid Inner Lock	damaged		\$581.45	4-10
49	1	Rear Boot Lid Inner Rubber	cut		\$371.85	✓
50	2	Rear Boot Lid Inner Trim Board	new	\$721.85	\$1,443.70	X
51	8	Rear Boot Lid Inner Trim Board Clip	new	\$6.50	\$52.00	X
52	2	Rear Tail Lamp	cracked	\$733.20	\$1,466.40	1100
53	4	Rear Tail Lamp Clip	new	\$6.50	\$26.00	✓
54	2	Rear Tail Lamp Lower Bracket	cracked	\$235.80	\$471.60	124
55	1	Rear Bumper	damaged		\$975.85	✓
56	8	Rear Bumper Clip	new	\$6.50	\$52.00	30
57	2	Rear Bumper Side Retainer	new	\$170.45	\$340.90	210
58	2	Rear Bumper Side Reflector	cracked		\$182.10	✓
59	1	Rear Bumper Lower	damaged		\$591.45	✓
60	1	Rear Bumper Inner Sponge	cracked		\$182.25	✓
61	1	Rear Bumper Reinforcement	best		\$371.75	✓
62	2	Rear Bumper Reinforcement Bracket	best	\$172.45	\$344.90	✓
63	4	Rear Bumper Parking Sensor	damaged		\$380.00	✓
64	1	Rear End Panel	damaged		\$781.10	✓
65	1	Rear End Panel Top Garnish	damaged		\$561.60	285
66	2	Rear Fender Inner Trim Board	new		\$581.90	X
67	16	Rear Fender Inner Trim Board Clip	new	\$6.50	\$104.00	X
68	1	Rear Spare Tyre Panel	new		\$975.75	X
69	1	Rear Spare Tyre Panel Top Cover	damaged		\$348.20	✓
70	1	Rear Spare Tyre Panel & End Panel Sealant	new		\$50.00	X

71	1	Rear Exhaust	2 x 4	\$781.10	X
72	1	Rear Centre Exhaust	1 pc	\$1,712.45	X

17837.67
16053.90

Subtotal :- \$45,468.96

Labour charges

To remove & refit rear cushion & trim board	\$280.00 80
To remove & refit rear & centre exhaust	\$380.00 X
To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 X
Remove & refit front & rear reverse sensor	\$250.00 120
To remove & refit reverse camera	\$180.00 50
To remove & refit & reset hybrid battery	\$1,000.00 X
Gum	\$50.00 X
To check wiring	\$100.00 60
Tuff kote	\$150.00 80
Panel beating	\$2,600.00 1500
Spray painting	\$2,200.00 1500

3390

Subtotal :- \$7,570.00

Total :- \$53,038.96

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

total 19443.90

2/s: 15.5K

10 Days

102/5
15.5K