

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 6426M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	TO REPAIR SEE LABOUR	1,655.21	-
1	BOOTLID REAR LOGO	NECESSARY	62.00	62.00
1	BOOTLID 'C200' EMBLEM	NECESSARY	82.00	82.00
1	BOOTLID '7G-TRONIC' EMBLEM	NECESSARY	65.00	65.00
1	BOOTLID CENTRE CHROME MOULDING	NECESSARY	194.00	194.00
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	288.39	-
1	REAR BUMPER	DENTED / DEFORMED	1,345.11	1,345.11
1	REAR BUMPER CHROME MOULDING CENTRE	CRACKED / NECESSARY	185.00	185.00
2	REAR BUMPER CHROME MOULDING SIDE L & R @\$115.00	CRACKED / NECESSARY	230.00	230.00
1	SET REAR BUMPER RIVET	NECESSARY	60.00	60.00
1	REAR BUMPER INNER TOP RETAINER	CRACKED	168.00	168.00
1	REAR BUMPER REINFORCEMENT	BENT	655.00	655.00
2	REAR BUMPER SIDE HOLDERS @\$45.00	CRACKED	90.00	90.00
2	REAR BUMPER PDC SENSORS @\$205.00	SHORTED	410.00	410.00
1	REAR END PANEL	DENTED	1,005.00	1,005.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	185.20	-
	LESS 10% DISCOUNT		-	-455.11
			6,679.91	4,096.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACING REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO RESET & REPROGRAMME SYSTEM		120.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID.		880.00	680.00
	TO PUTTY & SPRAY PAINTING.		1,280.00	1,000.00
			2,610.00	1,910.00

Report Ref No. CS/TP20009797/Uqf3e2



Page No.:2 of 2

GRAND TOTAL	9,289.91	6,006.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		4,800.00

Report Ref No. CS/TP20009797/Uqf3e2

CHUA KANG SENG

Licensed Appraiser