

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TAN YONG HEE

22 ST. MICHAEL'S ROAD #02-15

SINGAPORE 327981

Contact : 96356046

TP AXA.
Jasper.

ESTIMATE

Repair Code : CLM15009

Date in : 07/09/2020

Vehicle Num. : SMQ9957L

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11327442/L15B5577481

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>debond</i>	1	463.70	✓ 463.70
REAR BUMPER LOWER COVER <i>hol new</i>	1	250.00	X 250.00
REAR BUMPER SIDE L/R <i>RH Debond, LH Repair</i>	2	195.00	195 390.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	✓ 46.00
REAR END PANEL <i>Repair</i>	1	415.60	X 415.60
REAR END PANEL INNER TOP GARNISH <i>debond</i>	1	98.00	✓ 98.00
REAR FLOOR PANEL INNER TOP BOARD COVER <i>hol new</i>	1	430.30	X 430.30
REAR TAILGATE <i>Distorted</i>	1	953.30	✓ 953.30
REAR TAILGATE 'VEZEL' EMBLEM <i>new</i>	1	56.20	✓ 56.20
REAR TAILGATE INNER PULL GARNISH <i>hol new</i>	1	27.50	X 27.50
REAR TAILGATE INNER TRIM GARNISH <i>cracked</i>	1	153.40	✓ 153.40
REAR TAILGATE MECHANISM LOCK <i>damaged</i>	1	180.00	✓ 180.00
REAR TAILGATE OUTER GARNISH <i>cracked</i>	1	226.70	✓ 226.70
REAR TAILGATE OUTER GARNISH 'H' LOGO <i>new</i>	1	25.00	✓ 25.00
REAR TAILGATE REFLECTOR BACK RUBBER SEAL L/R <i>new</i>	2	38.50	✓ 77.00
REAR TAILGATE REFLECTOR L/R <i>cracked</i>	2	360.00	✓ 720.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>hol new</i>	2	18.50	X 37.00
REAR TAILGATE WEATHER STRIP <i>hol new</i>	1	96.80	X 96.80

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN YONG HEE
22 ST. MICHAEL'S ROAD #02-15
SINGAPORE 327981

Contact : 96356046

ESTIMATE

Repair Code : CLM15009

Date in : 07/09/2020

Vehicle Num. : SMQ9957L

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11327442/L15B5577481

REAR TAILGATE WINDSCREEN INNER SEAL	<i>3 new</i>	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN MOULDING		2	50.00	✓	100.00
REAR TAILLAMP L/R	<i>cracked.</i>	2	441.50	✓	883.00

Subtotal before discount 5,729.50

Percentage discount 20%

1,145.90

Sub-total 1

4,583.60

REAR BUMPER CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR - SET	<i>Damaged</i>	1	250.00	<i>20</i>	250.00
REAR NUMBER PLATE	<i>at car</i>	1	25.00	✓	25.00
REAR NUMBER PLATE HOLDER	<i>Not new</i>	1	50.00	<i>x</i>	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>new</i>	1	50.00	<i>20</i>	50.00
REAR TAILGATE REVERSE CAMERA	<i>Damaged.</i>	1	450.00	<i>380</i>	450.00
REAR TAILGATE WINDSCREEN SEALANT	<i>new</i>	1	60.00	✓	60.00
REAR TAILLAMP CLIPS L/R - SET	<i>new</i>	2	20.00	✓	40.00

Subtotal before discount 1,025.00

Percentage discount 0%

0.00

Sub-total 2

1,025.00

Parts-total

5,608.60

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TAN YONG HEE

22 ST. MICHAEL'S ROAD #02-15

SINGAPORE 327981

ESTIMATE

Repair Code : CLM15009

Date in : 07/09/2020

Vehicle Num. : SMQ9957L

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11327442/L15B5577481

Contact : 96356046

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

✓ 60.00

120 150.00

80 100.00

600 900.00

600 800.00

60 80.00

✓ 80.00

Labour Total

2,170.00

Parts & Labour Total

7,778.60

*** This is a computer-generated document which requires no signature.***

page 3

total: 5884.28

L/S: A. 7K.

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4.7K