

REPAIR ESTIMATE*

14/09/20

VEHICLE NO SHA1516Y

MAKE :

MODEL HYU- I40

CHIANG/AIG

QTY	Parts Description/ Labour	TYPE	Unit Price	Amount	
1	REAR BUMPER COVER			\$1,106.00	✓
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20	?
10	REAR BUMPER CLIPS		\$2.20	\$22.00	✓
1	REAR BUMPER LOWER COVER			\$228.00	Ry
1	REAR BUMPER REINFORCEMENT			\$428.40	?
1	REAR BUMPER STAY BRACKET LH/RH		\$80.30	\$160.60	?
1	REAR BUMPER UNDER COVER			\$228.00	?
1	BOOTLID GARNISH			\$227.90	?
1	BOOTLID			\$2,174.90	✓
1	BOOTLID HINGE LH			\$142.30	Ry
1	BOOTLID UPPER LOCK			\$114.90	?
1	BOOTLID CRDI PLATE			\$27.90	✓
1	BOOTLID I-40 PLATE			\$21.10	✓
	SUB TOTAL			\$4,953.20	
	20.00%			\$990.64	
	DISCOUNTED TOTAL			\$3,962.56	
1	BOOTLID COMFORT LOGO			\$30.00	✓
1	BOOTLID COMFORT TEL NO			\$30.00	✓
1	BUMPERRUBBER MAT			\$50.00	✓
1	REVERSE SENSOR			\$135.70	✓
				\$245.70	
	Labour Charge				
	Panel Beating			\$540.00	420
	Spray Painting Charge			\$500.00	400
	Remove/refix reverse sensor			\$60.00	30
	Tuff Kote			\$120.00	30
	Check Lighting			\$60.00	30
	TOTAL LABOUR			\$1,280.00	
	ESTIMATE TOTAL			\$5,488.26	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tan Kah 97415747
 WP 14/9/20 03pm
 4/5 Resurvey after repair. within
 Tan Kah 14/9/20. with
 Tan Kah

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

A number of COMFORTDELGRO

Date/Time: 14.09.2020 10:38

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:


JC NO: 305422340

CUSTOMER NAME COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO:	SHA1516Y	MILEAGE
	MAKE:	HYUNDAI	FUEL
	MODEL	I-40	DATE/TIME IN
	YR OF MANU.	12.05.2016	TARGET DATE
	CHASSIS CODE	KMHLB41UMGU090108	COMPLETION DATE/TIME:
	COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 12.09.2020
NATURE: 3P 12.09.2020

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SHA1516Y CHIANG

Vehicle No.: SHA1516Y

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard