



Exceptional Journeys

Surveyor : RASUL LKK
Claim : AIG OD
DOA : 13.09.2020
Emailed : 12.10.2020, 1pm
Date Survey : 14.09.2020

VEHICLE NO : SKS 1039 C
MODEL : MIT OUTLANDER 2.4
WIP : 57305

Material	:	\$	<u>8,787.24</u>
Labour	:	\$	<u>4,125.00</u>
Sub-Total	:	\$	<u>12,912.24</u>
	:		<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>12,312.24</u>
GST 7%	:	\$	<u>861.86</u>
Grand Total	:	\$	<u>13,174.10</u>
Finalise By/Date	:		<u>LOI / 12/10/2020</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK _____ WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name KCV13801/Mr Tan Peng Seng (chen Bingchen)
MOTOR CLAIM DEPT	Reg No/Reg Date SKS1039C / 25/03/2015
78 SHENTON WAY #08-16	Date In/Mileage 17/09/2020/ 114063
AIG BUILDING	Chassis/Package JMYXTGF3WFZ001657 /DC17P
SINGAPORE 079120	Engine No 4B12PG7136
Contact No 6419 1892	Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27)
21/09/2020	Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	12/10/2020/ 10:51	BLD	260 / AiTing	57305				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, RH FRONT FENDER, RH MOULDING GARNISH, REPAIR REAR BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								1125.00
E PNT88000	REMOVE AND INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR								60.00
E PNT98000	RESPRAY ON FRONT BUMPER, RH FRONT FENDER, REAR BUMPER, AND ALL OTHER AFFECTED PORTIONS TO THE SAME								1050.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901	CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								120.00
A 30000001	REMOVE & REPLACE RH FRONT UNDER CARRIAGE PARTS INCLUDING FRONT AXLE CROSS MEMBER								450.00
A WHEELALIGNMENTBP	CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								120.00
M SUNDRY	REMOVE & REPLACE RH FRONT AND RH REAR SPORTS RIMS,REPLACE TIRE VALVES, AND CONDUCT WHEEL BALANCING								60.00
M SUNDRY	SUNDRIES								30.00
S TYRESALES2	SUPPLY RH FRONT AND RH REAR TIRES (\$400 + \$400)								800.00
X EXC	INSURANCE EXCESS								-600.00
S SPECIALISTJOB	SUPPLY FRONT PARKING ASSIST SENSOR WITH DISTANCE INDICATOR (A)								280.00
X HEADLAMP ASSY,RH					1.00	1852.00	23.00	1426.04	
X BRACKET,FR BUMPER SIDE,RH					1.00	24.00	23.00	18.48	
X FACE,FR BUMPER					1.00	1036.00	23.00	797.72	
X GARNISH,FR FOG LAMP,RH					1.00	50.00	23.00	38.50	

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV13801/Mr Tan Peng Seng (chen Bingchen) Reg No/Reg Date SKS1039C / 25/03/2015 Date In/Mileage 17/09/2020/ 114063 Chassis/Package JMYXTGF3WFZ001657 /DC17P Engine No 4B12PG7136 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim U01 / BK
21/09/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	12/10/2020/ 10:51	BLD	260 / AiTing	57305		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	MOULDING,FR BUMPER,RH			1.00	✓ 116.00	23.00	89.32
X	MOULDING,RR WHEEL ARCH,RH			1.00	✓ 199.00	23.00	153.23
X	MOULDING,RR BUMPER,RH			1.00	✓ 106.00	23.00	81.62
X	FENDER,FR RH			1.00	✓ 688.00	23.00	529.76
X	HUB ASSY,FR WHEEL			1.00	✓ 235.00	23.00	180.95
X	SNAP RING,FR WHEEL HUB			1.00	✓ 25.00	23.00	19.25
X	BEARING,FR WHEEL HUB			1.00	✓ 151.00	23.00	116.27
X	KNUCKLE,RH			1.00	✓ 356.00	23.00	274.12
X	ARM ASSY,FR SUSP,LWR RH			1.00	✓ 337.00	23.00	259.49
X	CROSSMEMBER,FR AXLE,NO.1			1.00	✓ 1114.00	23.00	857.78
X	STRUT,FR SUSP,RH			1.00	✓ 484.00	23.00	372.68
X	END ASSY,TIE ROD			1.00	✓ 62.00	23.00	47.74
X	RH FRONT WHEEL,DISC			1.00	✓ 1102.00	23.00	848.54
X	RH REAR WHEEL,DISC			1.00	✓ 1102.00	23.00	848.54
X	GEAR & LINK ASSY,STEERING			1.00	✓ 1211.00	23.00	932.47
X	LINK,FR SUSP STABILIZER			1.00	✓ 137.00	23.00	105.49
X	BEARING,FR SUSP STRUT			1.00	✓ 32.00	23.00	24.64
X	HUB ASSY,RR WHEEL			1.00	✓ 414.00	23.00	318.78
X	SHIELD,FR WHEELHOUSE,RH			1.00	✓ 164.00	23.00	126.28
X	MOULDING,FR WHEEL ARCH,RH			1.00	✓ 199.00	23.00	153.23
X	CLIP,ENG ROOM COVER			5.00	✓ 2.00	23.00	7.70
X	CLIP,RR BUMPER			6.00	✓ 3.00	23.00	13.86
X	GARNISH,FR BUMPER,RH			1.00	? 32.00	23.00	24.64
X	MOTOR,WINDSHIELD WASHER(*)			1.00	✓ 156.00	23.00	120.12
Z	TEXT						
	AIG OD CLAIM						
	DOA : 13.09.20						
	SURVEYOR RASUL LKK 14.09.20						
	POLICY NO : 2100406599-05						

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	8,787.24	Nett	12,312.24
Labour	2,955.00	7% GST on	12312.24
Standard Menu	0.00		861.86
Specialist Job	1,080.00	Total Payable	13,174.10
Diagnostics Job	0.00		
Sundry/Others	-510.00		
Total(w/o GST)	12,312.24		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SKS 1039 C

	<u>Material</u>	<u>Cost (\$)</u>
1	Bearing, fr susp strut	32.00
2	Hub assy, RR wheel	414.00
3	Shield, Fr wheelhouse, RH	164.00
2	Moulding, Fr wheel arch, RH	199.00
4	Clips (x5)	10.00
5	Clips (x6)	18.00
3	Motor, windshield washer	156.00
		<hr/> 993.00
	Less 23%	228.39
	<hr/> Total Materials	<hr/> 764.61
	7% GST	53.52
	Grand total	<u>\$ 818.13</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
DID : 6568 4556 / 4501
FAX : 6567 5258 / 6565 1240

R001194
SKS1039C
In: ALVIN (108)
e: 114066
29.9.20 9:46

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : All Wheel Drive

Front : Left

Actual	Before	Specified Range
0°07'	0°08'	-0°10' 0°50'
2°09'	2°08'	2°05' 3°05'
0°04'	0°00'	-0°02' 0°06'
16°55**	17°00**	11°15' 14°15'
17°02**	17°08**	11°05' 15°05'

Camber
Caster
Toe
SAI

Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°29'	0°28'	-0°10' 0°50'
2°36'	2°40'	2°05' 3°05'
-0°01'	0°04'	-0°02' 0°06'
17°40**	17°39**	11°15' 14°15'
18°10**	18°08**	11°05' 15°05'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°22'	-0°20'	-0°30' 0°30'
-0°27'	-0°33**	-0°30' 0°30'
-0°45'	-0°40'	
0°04'	0°04'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-1°11'	-1°33**	-1°15' 0°15'
0°05'	0°04'	0°02' 0°12'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°52'	-0°52'	-1°15' 0°15'
0°06'	0°07'	0°02' 0°12'

Rear

Cross Camber
Total Toe
Thrust Angle


Actual	Before	Specified Range
-0°19'	-0°41**	-0°30' 0°30'
0°11'	0°11'	0°04' 0°24'
-0°01'	-0°01'	

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	GF3W 2014MY

SKS 1039 C.

FD H.O.T. II Day, chh-

↳ Read & Clear All DTC. 



All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14000000		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS (A.S.C.)	ABS_40080015		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS (Can't see P/N on ECU body)	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AWC	AWC_16080002		No DTCs	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN (Can see P/N on ECU body)	ETACS_83040801		Non-target System	

All DTCs

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	Power Gate	ETG_92080000	U0184	AUDIO CAN timeout		Active
	KOS/IMMO/Keyless (IMMOBI & KOS)	KOS_8A880020		No DTCs		
	OSS	OSS_9588000B		No DTCs		
	CORNER SENSOR/BACK SENSOR	CornerSens_96000001		Non-equipped System or Communication Error		