



CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 ATG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV13801/Mr Tan Peng Seng (chen Bingchen) Reg No/Reg Date SKS1039C / 25/03/201 Date In/Mileage / 114063 Chassis No JMYXTGF3WFZ001657 Engine No 4B12PG7136 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	14/09/2020/ 11:26	QUD	247 / DonBong	57305			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, RH FRONT FENDER, RH MOULDING GARNISH, REPAIR REAR BUMPER FACE								1125 1350.00
E PNT88000 REMOVE AND INSTALL FRONT PARKING ASSIST								60.00
E PNT98000 PAINT WORK SPRAY FRONT BUMPER, RH FRONT FENDER, BOTH RH DOOR, REAR BUMPER FACE AND AFFECTED PORTION								1050 2100.00
M SUNDRY APPLY BODY SEALANT								X 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
A 30000001 RENEW UNDERCARRIAGE DAMAGES								450? 575.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY LABOUR RENEW RH FRONT AND RH REAR SPORT RIM INCLUDING BALANCING								60.00
M SUNDRY SUPPLY RH FRONT AND RH REAR TIRE								400 (112) 800.00
M SUNDRY SUNDRIES								30 50.00
M HEADLAMP ASSY, RH					1.00	1852.00	23.00	1426.04
M TANK, WINDSHIELD WASHER					1.00	88.00	23.00	67.76
M MOTOR, HEADLAMP WASHER					1.00	354.00	23.00	272.58
M GROMMET, WINDSHIELD WASHER					1.00	5.00	23.00	3.85
M COVER, ENG ROOM UNDER, RR RH					1.00	32.00	23.00	24.64
M COVER, ENG ROOM UNDER, RR LH					1.00	32.00	23.00	24.64
M COVER, ENG ROOM UNDER, FR					1.00	348.00	23.00	267.96

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.