

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details				
Registration Number	SMB3C			
Case Reference Number	BUS/09/20/1002			
Registration Date	16/9/2008			
Company Type	SMRT Buses Ltd			
Make	MERCEDES			
Model	MBOC500			
Name of Driver	Tan Choon Seng			
Type of Accident	Side Swipe			
Accident Date and Time	2/9/2020 3:07 PM			
Accident Reported Date and Time	2/9/2020 4:45 PM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number	24108103			
Special Instruction to ARC,if any	SMB3C-RIGHT CENTER PORTION SMG4560H (TP) INSURED WITH NTUC			
Prepared Date and Time	7/9/2020 1:41 PM			
Chassis Number	WEB63442021000060			
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Repa	ir Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$2,120.00	\$1,590.00			
Total Spray Cost	\$1,112.00	\$942.00			
Total Spare Part Cost	\$2,499.98	\$1,440.71			
Total Other Cost	\$0.00	(\$506.40)			
TOTAL COST	\$5,731.98	\$3,466.31			
Lump Sum Total	\$5,750.00	\$3,450.00			
Number of Repair Days	6.0	4.0			
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)			
ARC / Surveyor Sign Off Date	07/09/2020 1:50 PM	09/09/2020 11:25 AM			
Signature		5			
Remarks					

Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/09/2020
User ID : CatherineLee



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/09/2020
User ID : CatherineLee

			Section	on D - Deta	ils of Repair E	stimates			
Part 1 - Labo	ur Works								
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS			\$2,120.00				\$1,590.00		
DAMAGED AFFECTED AREAS.			\$2,120.00				\$1,590.00		
	/ Painting & Pan	el Beating Rela		φ2,120.00				<u> </u>	
Job Scope			Quotation fr	om ARC			Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$1,112.00				\$942.00		
	inting & Panel Be	ating		\$1,112.00				\$942.00	
Part 3 - Other	Costs - Accider	nt and Acciden	t Repair Related Expens	se				•	
· · · · · · · · · · · · · · · · · · ·								Adjusted by Surveyor, if applicable	
Lump Sum Adju	stment by Surveyo	or		\$0.00				(\$506.40)	
Total Other Co	sts			\$0.00				(\$506.40)	
Part 4 - Spare	Parts / Material	Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace / Nec
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	Replace / Nec
6010227	BODY RH	5019	PANEL,SKIRT:R4,FOR MB OC500 BUS	1.00	\$1,442.10	10.00	\$1,297.89	Replace	Replace / bb
6010228	BODY RH	5020	PANEL,SKIRT:R5,FOR MB OC500 BUS	1.00	\$72.50	100.00	\$0.00	Replace	Repair X R
6010229	BODY RH	5021	PANEL,SKIRT:R6,FOR MB OC500 BUS	1.00	\$518.20	100.00	\$0.00	Replace	Repair X R
6010230	BODY RH	5022	PANEL,SKIRT:R7,FOR MB OC500 BUS	1.00	\$880.50	100.00	\$0.00	Replace	Repair 🗶 K
4006313	CONSUMABLE	SIKA® Primer- 206 G+P		1.00	\$80.00	0.00	\$80.00	Replace	Replace / hlec
	CONSUMABLE		SEALANT:SIKATACK- MOVE TRANSPORTATION	4.00	\$37.00	0.00	\$148.00	Replace	Replace /Nec
Total					\$3,305.30		\$1,800.89		
Added Spare	Parts / Material	Usage After Su	rveyor Signed off	•	•	•	•		
					l	In	I=	I.z.a.a.	la
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

4/5 \$3,450 4 days 1,800.89 1,590 942 4,332.89 - 20% 3,466.31

Total