



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2008109
INV Date 03/12/2020
Reference CC4/FCI20009807/Kds3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKV 1080R
Insured Veh. SHA 3107G
Claim No. D20003675MFSH
Policy No. D-20094922MFSH
Accident Date 08/09/2020
Inspection Date 18/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20009807/Kds3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-12-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3107G	Veh. Inspected	SKV 1080R
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003675MFSH	Excess (\$)	0.00
Assign From	CHRIS LIM	Assign Date	14/09/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MHFZ28H3500054722	Colour	METALLIC GREY
Odometer	43895	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	8 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	8 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/09/2020	Inspection Date	18/09/2020
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 1080R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RH SIDE MIRROR ASSY	CRACKED	872.20	872.20
	LESS 25% DISCOUNT		-218.05	-218.05
			654.15	654.15
	LABOUR			
	TO REMOVE & RENEW RH SIDE MIRROR .		60.00	60.00
	TO PUTTY AND SPRAY RH SIDE MIRROR BACK COVER .		50.00	50.00
			110.00	110.00
	GRAND TOTAL		764.15	764.15
RECOMMENDED COST OF REPAIRS				764.15

Report Ref No. CC4/FCI20009807/Kds3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 1080R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

