

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06232

Date : 09-Sep-2020

Vehicle Insured : SHA3107G
Accident Date : 09-Sep-2020

PAGE : 1

Our Ref : 020113 (FIRST) / CHAN

HAN LIH KWONG
7 LANGE ROAD
Singapore 547975

*Not available
Running by pain 1 day*

ESTIMATED COST OF REPAIR FOR TOYOTA SIENTA 1.5 CVT STD(A) SKV1080R
=====

1 pc RH side mirror assy	<i>C/M</i> 872.20 ✓	
	872.20	
Less 25% :	218.05	
	-----	654.15
To remove & renew rh side mirror		60.00 ✓
To putty and spray rh side mirror back cover		50.00 ✓

Total :	S\$	764.15
		=====

Singapore Dollars Seven Hundred and Sixty Four
and Cents Fifteen Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: