

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLV 2410 D

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 12/09/2020

TP Veh Reg No: SFE6157U

Estimate No: ES2090714/YISHUN

Date: 14 Sep 2020

Policy No: 5096904063-02

Veh Reg No: SLV2410D

Make/Model: HONDA VEZEL

Chassis No: RU31265203

Engine No: LEB596223

Reg. Date: 26/12/2017

Not Authored

Running Bqram

6-10 days

Estimate Repair Cost to Vehicle No :SLV2410D

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	801.70	1 PC	801.70	✓
2 FRONT BUMPER REINFORCEMENT	360.80	1 PC	360.80	✓
3 FRONT BUMPER LH FOG LAMP	327.70	1 PC	327.70	✓
4 FRONT BUMPER LH FOG LAMP GARNISH	40.50	1 PC	40.50	✓
5 FRONT BUMPER LH FOG LAMP BRACKET	17.10	1 PC	17.10	?
6 FRONT BUMPER CENTRE LOWER GRILLE	77.50	1 PC	77.50	?
7 FRONT BUMPER SIDE RETAINERS	14.70	2 PCS	29.40	✓
8 FRONT BUMPER LOWER SKIRT RUBBER	381.00	1 PC	381.00	?
9 FRONT BUMPER CLIPS	3.90	6 PCS	23.40	✓
10 FRONT BUMPER DAY LIGHT	234.10	1 PC	234.10	?
11 FRONT LH FENDER	558.70	1 PC	558.70	✓
12 FRONT LH FENDER EMBLEM "HYBRID"	76.60	1 PC	76.60	✓
13 FRONT LH FENDER INNER SHIELD	130.60	1 PC	130.60	✓
14 FRONT LH FENDER INNER SHIELD CLIPS	3.90	6 PCS	23.40	✓
15 FRONT LH FENDER INNER PANEL	409.70	1 PC	409.70	?
16 FRONT LH FENDER WHEEL ARP GARNISH	199.20	1 PC	199.20	✓
17 BONNET	892.30	1 PC	892.30	✓
18 BONNET INNER RUBBER	24.50	1 PC	24.50	✓
19 BONNET LH HINGE	48.50	1 PC	48.50	?
20 BONNET INNER SPONGE	122.30	1 PC	122.30	X
21 BONNET INNER SPONGE CLIPS	3.90	6 PCS	23.40	X
22 FRONT RH FENDER EMBLEM "HYBRID"	75.00	1 PC	75.00	✓
23 FRONT GRILLE BASE	351.80	1 PC	351.80	✓
24 FRONT GRILLE OUTER GARNISH	401.20	1 PC	401.20	✓
25 FRONT GRILLE LOGO	27.40	1 PC	27.40	✓
26 FRONT GRILLE CHROME MOULDING	95.00	1 PC	95.00	?
27 FRONT GRILLE CLIPS	3.90	6 PCS	23.40	✓
28 LH HEADLAMP	1,923.50	1 PC	1,923.50	✓
29 LH HEADLAMP LOWER GARNISH	35.00	1 PC	35.00	✓
30 FRT SUPPORT PANEL	576.20	1 PC	576.20	?
31 RADIATOR	1,376.50	1 PC	1,376.50	?
32 AIR FILTER HOUSING LOWER	175.00	1 PC	175.00	?
33 AIR FILTER RESONATOR	90.10	1 PC	90.10	?
34 FRONT WIPER GARNISH	240.00	1 PC	240.00	X
35 FRONT RH FENDER WHEEL ARP GARNISH	195.00	1 PC	195.00	✓
36 FRONT LH SHOCK ABSORBER	430.10	1 PC	430.10	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 12/09/2020
TP Veh Reg No: SFE6157U

Estimate No: ES2090714/YISHUN
Date: 14 Sep 2020
Policy No: 5096904063-02
Veh Reg No: SLV2410D
Make/Model: HONDA VEZEL
Chassis No: RU31265203
Engine No: LEB596223
Reg. Date: 26/12/2017

Estimate Repair Cost to Vehicle No :SLV2410D

Description	U/Price	Quantity	List Price S\$	Amount S\$
			10,817.60	
		Less 20%	2,163.52	8,654.08
Special Net				
37 FRONT LH TYRE	230.00	1 PC	230.00	230.00
Labour				
38 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	?
39 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT FENDER,BONNET & ATTACHMENT,RADIATOR & MOTOR,CUT,WELD & RENEW FRT SUPPORT PANEL,FRT LH FENDER INNER PANEL & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
40 REMOVE & REFIX FRT LH SHOCK ABSORBER	100.00	1 LA	100.00	?
41 REMOVE & REFIX ENGINE,ECU,ENGINE MOUNTINGS,ETC AND RESET SYSTEM	350.00	1 LA	350.00	?
42 PUTTY & RESPRAY ON FRT LH DOOR,FRT BUMPER,BONNET,SUPPORT PANEL,FRT LH WHEEL HOUSING	1,100.00	1 LA	1,100.00	1000
43 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	
44 RUSTPROOFING	80.00	1 LA	80.00	
			2,990.00	2,990.00
Total				S\$ 11,874.08

Add GST @ 7% 831.19

Total Amount Payable S\$ 12,705.27

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE