



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101688

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 16/03/2021
Reference CC4/FCI20009817/Ara3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMT 7358M
Insured Veh. SHD 4369U
Claim No. D20003694MFSH
Policy No. D-20094922MFSH
Accident Date 09/09/2020
Inspection Date 15/09/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI20009817/Ara3q2

Date: 16/03/2021

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4369U	Veh. Inspected	SMT 7358M
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003694MFSH	Excess (\$)	0.00
Assign From	VIC	Assign Date	14/09/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	KMHD841CMLU085615	Colour	GREY
Odometer	3772 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/09/2020	Inspection Date	15/09/2020
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 7358M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	BUCKLED	1,853.60	1,853.60
1	REAR BOOTLID SMARTKEY ANTENNA	CRACKED	197.50	197.50
2	REAR BOOTLID NUMBER PLATE LAMPS @\$85.20	NOT NECESSARY	170.40	-
1	REAR BOOTLID INNER LOCK	DAMAGED	195.80	195.80
1	REAR BOOTLID INNER TRIM	NOT NECESSARY	406.20	-
1	REAR BOOTLID LATCH	NOT NECESSARY	38.50	-
1	REAR BOOTLID LOGO	NECESSARY	79.60	79.60
1	REAR BOOTLID 'AVANTE' EMBLEM	NECESSARY	98.70	98.70
1	REAR BOOTLID 'S' EMBLEM	NECESSARY	76.80	76.80
2	REAR BOOTLID LAMPS @\$498.70	O/S CRACKED	997.40	498.70
1	REAR BOOTLID WEATHERSTRIP	CUT	145.60	145.60
1	END PANEL	DENTED	657.80	657.80
1	END PANEL TOP GARNISH	DEFORMED	175.90	175.90
1	END PANEL BOOT RELEASE ANTENNA	CRACKED	185.90	185.90
1	SPARE TYRE FLOOR PANEL	TO REPAIR SEE LABOUR	685.70	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	398.60	-
2	TAILLAMPS @\$758.60	CRACKED	1,517.20	1,517.20
2	TAILLAMPS INNER SEALER @\$40.00	NOT NECESSARY	80.00	-
1	REAR BUMPER	DEFORMED	598.70	598.70
1	REAR BUMPER NUMBER PLATE GARNISH	DEFORMED	78.60	78.60
1	REAR BUMPER LOWER	CRACKED	496.30	496.30
1	REAR BUMPER LOWER COVER LH	NOT NECESSARY	197.80	-
1	REAR BUMPER LOWER COVER RH	NOT NECESSARY	156.30	-
2	REAR BUMPER RETAINERS @\$85.90	NECESSARY	171.80	171.80
2	REAR BUMPER REFLECTOR @\$256.80	O/S CUT	513.60	256.80
1	REAR BUMPER REINFORCEMENT	CRACKED	398.70	398.70
3	REINFORCEMENT BRACKETS (BOTTOM)@\$76.80	DAMAGED	230.40	60.00
2	REINFORCEMENT BRACKETS (TOP) @\$76.80	DAMAGED	153.60	40.00
2	REAR FENDER INNER COWLING @\$165.90	NOT NECESSARY	331.80	-
2	REAR FENDER AIR DUCTS @\$98.50	NOT NECESSARY	197.00	-

Report Ref No. CC4/FCI20009817/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,297.16	-1,556.80
			9,188.64	6,227.20
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	CRACKED	50.00	50.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
2	SET TAILLAMPS CLIPS (SN)	NECESSARY	60.00	20.00
1	SET END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
2	END PANEL SEALANT (SN)	NECESSARY	80.00	60.00
2	SET REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER LOWER COVER CLIPS (SN)	NECESSARY	30.00	20.00
			590.00	390.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS ,REPLACE BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS.INCLUSIVE OF THE REPAIR OF SPARE TYRE FLOOR PANEL .		1,800.00	1,000.00
	TO RESPRAY AFFECTED AREAS.		1,800.00	800.00
	TO TUFFCOAT AFFECTED AREA.		200.00	60.00
	TO CONDUCT WIRING CHECK ON THE REAR TAILLAMPS.		120.00	30.00
	TO REMOVE /REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING.		180.00	20.00
	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY.		180.00	60.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	TO REMOVE AND REPLACE BOOTLID MECHANISM		150.00	60.00
			4,550.00	2,030.00
	GRAND TOTAL		14,328.64	8,647.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,800.00

Report Ref No. CC4/FCI20009817/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 7358M

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 7358M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

