

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KHOO LENG HOW
BLK 13 JOO SENG ROAD #05-63
SINGAPORE 360013

Contact : 91999889, 96456465

TP Lon Pac.
Cecilia.

ESTIMATE

Repair Code : CLM15014

Date in : 14/09/2020

Vehicle Num. : EZ3113S

Model : MERCEDES BENZ A200 AMG LINE AUTO

Chassis/Eng# : WDD1770872J026828/28291480017658

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Dented.</i>	1	1510.00	✓ 1,510.00
FRONT LH DOOR CHECKER <i>new</i>	1	55.00	✗ 55.00
FRONT LH DOOR GLASS CONTROL MODULE <i>new</i>	1	598.00	✗ 598.00
FRONT LH DOOR GLASS OUTER CHROME MOULDING <i>new</i>	1	235.00	✗ 235.00
FRONT LH DOOR GLASS REGULATOR <i>Damaged</i>	1	568.00	✓ 568.00
FRONT LH DOOR GLASS REGULATOR MOTOR <i>Damaged</i>	1	495.00	✗ 495.00
FRONT LH DOOR HANDLE INNER BRACKET <i>new</i>	1	180.00	✓ 180.00
FRONT LH DOOR HINGE (LOWER) <i>new</i>	1	98.00	✗ 98.00
FRONT LH DOOR HINGE (TOP) <i>new</i>	1	110.00	✗ 110.00
FRONT LH DOOR INNER TRIM BOARD <i>new</i>	1	620.00	✓ 620.00
FRONT LH DOOR MECHANISM LOCK <i>Damaged</i>	1	598.00	✓ 598.00
FRONT LH DOOR OUTER HANDLE <i>Damaged</i>	1	520.00	320.00 520.00
FRONT LH DOOR SIDE MIRROR <i>Damaged</i>	1	680.00	✓ 680.00
FRONT LH DOOR SIDE MIRROR COVER <i>new</i>	1	235.00	✓ 235.00
FRONT LH DOOR SIDE MIRROR GLASS <i>new</i>	1	290.00	✗ 290.00
FRONT LH DOOR SIDE MIRROR SIGNAL LAMP <i>missing</i>	1	198.00	✓ 198.00
FRONT LH DOOR WEATHER STRIP <i>new</i>	1	318.00	✓ 318.00
FRONT LH FENDER <i>Repair</i>	1	656.00	✗ 656.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KHOO LENG HOW
BLK 13 JOO SENG ROAD #05-63
SINGAPORE 360013

Contact : 91999889, 96456465

ESTIMATE

Repair Code : CLM15014

Date in : 14/09/2020

Vehicle Num. : EZ3113S

Model : MERCEDES BENZ A200 AMG LINE AUTO

Chassis/Eng# : WDD1770872J026828/28291480017658

REAR BUMPER <i>torn</i>	1	1668.00	1380 1,668.00
REAR BUMPER LH REVERSE SENSOR <i>3 new</i>	1	190.00	X 190.00
REAR BUMPER LH REVERSE SENSOR 'O' RING <i>3 new</i>	1	14.00	X 14.00
REAR BUMPER SIDE RETAINER L/R <i>2 new</i>	2	103.00	X 206.00
REAR H UPPER ARM <i>3 new</i>	1	198.00	X 198.00
REAR LH CONTROL ARM <i>3 new</i>	1	235.00	X 235.00
REAR LH DOOR <i>Dented</i>	1	1786.00	/ 1,786.00
REAR LH DOOR CHECKER <i>new</i>	1	96.00	X 96.00
REAR LH DOOR HINGE (LOWER) <i>3 new</i>	1	112.00	X 112.00
REAR LH DOOR HINGE (TOP) <i>3 new</i>	1	111.00	X 111.00
REAR LH DOOR WEATHER STRIP <i>new</i>	1	318.00	✓ 318.00
REAR LH FENDER <i>Repair</i>	1	2995.00	X 2,995.00
REAR LH FENDER INNER SHIELD <i>new</i>	1	145.00	X 145.00
REAR LH KNUCKLE ARM <i>3 new</i>	1	1460.00	X 1,460.00
REAR LH KNUCKLE ARM BEARING <i>3 new</i>	1	480.00	X 480.00
REAR LH LOWER ARM <i>3 new</i>	1	240.00	X 240.00
REAR LH SHOCK ABSORBER <i>3 new</i>	1	397.00	X 397.00
REAR LH SPORT RIM (AMG) <i>cut</i>	1	1500.00	1,500.00

900

~~1000~~ (SN)

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KHOO LENG HOW
BLK 13 JOO SENG ROAD #05-63
SINGAPORE 360013

Contact : 91999889, 96456465

ESTIMATE

Repair Code : CLM15014

Date in : 14/09/2020

Vehicle Num. : EZ3113S

Model : MERCEDES BENZ A200 AMG LINE AUTO

Chassis/Eng# : WDD1770872J026828/28291480017658

	9206	Subtotal before discount	20,115.00
Percentage discount 10%	9006 S.N. 900		2,011.50
	8105.40	Sub-total 1	18,103.50
FRONT LH DOOR INNER INSULATOR MAT <i>new</i>	8285.40	1	300.00 <i>X</i> 300.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>		1	50.00 <i>X</i> 50.00
REAR BUMPER CLIPS - SET <i>new</i>		1	80.00 <i>X</i> 80.00
REAR LH 225/45R18 TYRE <i>new</i>	60	1	550.00 <i>X</i> 550.00
REAR LH DOOR INNER INSULATOR MAT <i>2 new</i>		1	300.00 <i>X</i> 300.00
REAR LH FENDER INNER SHIELD CLIPS - SET <i>new</i>		1	50.00 <i>X</i> 50.00
		Subtotal before discount	1,330.00
Percentage discount 0%			0.00
		Sub-total 2	1,330.00
		Parts-total	19,433.50

LABOUR

To reset system after repair works

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall petrol tank. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

X 400.00

X 280.00

80 *X* 120.00

X 80.00

60 *X* 120.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KHOO LENG HOW
BLK 13 JOO SENG ROAD #05-63
SINGAPORE 360013

Contact : 91999889, 96456465

ESTIMATE

Repair Code : CLM15014

Date in : 14/09/2020

Vehicle Num. : EZ3113S

Model : MERCEDES BENZ A200 AMG LINE AUTO

Chassis/Eng# : WDD1770872J026828/28291480017658

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

nn ~~160.00~~
~~1100~~ 1,400.00
~~700~~ 1,100.00
~~60~~ 120.00

Labour Total

3,780.00

Parts & Labour Total

23,213.50

*** This is a computer-generated document which requires no signature.***

page 4

11,245.40

total 11065.40

1/s: 8.8K.

06 Days. ✓

8.8K ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: