

✓ 1136.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT6737X**
 MODEL : **TOYOTA SIENTA**
 DATE OF ACCIDENT : 13.09.20
 TIME OF ACCIDENT : 17:00HRS

30	FRONT DOOR SPEAKER RH <i>new</i>	1	\$ 213.10	\$ 213.10	+
31	FRONT DOOR PILLAR RH(OUTER) <i>Repis</i>	1	\$ 697.90	\$ 697.90	+
32	FRONT DOOR STEP PANEL INNER GARNISH (OUTER) <i>new</i>	1	\$ 188.45	\$ 188.45	+
33	ROCKER PANEL RH <i>Repis</i>	1	\$ 495.60	\$ 495.60	+
34	CENTER PILLAR RH (OUTER) <i>Repis</i>	1	\$ 382.70	\$ 382.70	+
35	CENTER PILLAR STICKER <i>new</i>	3	\$ 32.20	\$ 96.60	-
36	SLINDING DOOR RH <i>Distorted</i>	1	\$ 1,294.90	\$ 1,294.90	✓
37	SLINDING DOOR REFLECTOR STICKER RH <i>new</i>	1	\$ 39.70	\$ 39.70	5(SW)
38	SLIDING DOOR LOWER GUARD RH <i>Missing</i>	1	\$ 147.80	\$ 147.80	✓
39	SLINDING DOOR STEP PANEL GARNISH RH <i>new</i>	1	\$ 138.60	\$ 138.60	✓
40	SLINDING DOOR STOPPER (BACK) <i>new</i>	1	\$ 32.60	\$ 32.60	+
41	SLINDING DOOR ALIGN STOPPER (FRONT) <i>new</i>	2	\$ 25.80	\$ 51.60	+
42	SLINDING DOOR LOWER ROLLER RH <i>Best</i>	3	\$ 333.20	\$ 999.60	333.20
43	SLIDING DOOR LOWER RAILWAY PANEL RH <i>new</i>	1	\$ 642.10	\$ 642.10	+
44	SLIDING DOOR OUTER STRIP RH <i>new</i>	1	\$ 128.70	\$ 128.70	+
45	SLINDING DOOR INNER LOCK RH (FRONT) <i>new</i>	1	\$ 238.90	\$ 238.90	✓
46	SLINDING DOOR INNER LOCK RH (BACK) <i>new</i>	1	\$ 1,092.80	\$ 1,092.80	+
47	SLINDING DOOR FRAME WEATHERSTRIP RH <i>new</i>	1	\$ 409.60	\$ 409.60	+
48	SLIDING DOOR INNER TRIM RH <i>new</i>	1	\$ 800.20	\$ 800.20	✓
49	REAR FENDER LOWER GUARD RH <i>new</i>	1	\$ 128.70	\$ 128.70	✓
50	REAR ABS SENSOR RH <i>new</i>	1	\$ 397.10	\$ 397.10	+
51	REAR AXLE <i>2</i>	1	\$ 3,574.20	\$ 3,574.20	+
52	REAR WHEEL HUP CAP RH <i>new</i>	1	\$ 193.70	\$ 193.70	+
53	REAR WHEEL HUP WITH BEARING RH <i>new</i>	1	\$ 863.20	\$ 863.20	+
54	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 436.70	\$ 436.70	+

8902.40
6676.80

TOTAL PRICE \$ 27,621.65
 LESS 25% \$ 6,905.41
SUB TOTAL PRICE \$ 20,716.24

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT FENDER INNER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
4	FRONT WINDSCREEN SEALANT <i>3 All</i>	1	\$ 80.00	\$ 80.00	+
5	FRONT WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00	+
6	FRONT DOOR SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	+
7	FRONT DOOR INNER TRIM BOARD CLIP RH (SE) <i>new</i>	1	\$ 50.00	\$ 50.00	30
8	DASHBOARD (UPPER) CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT6737X**
 MODEL : **TOYOTA SIENTA**
 DATE OF ACCIDENT : 13.09.20
 TIME OF ACCIDENT : 17:00HRS

9	FRONT PILLAR SEALANT <i>3 NE</i>	1	\$ 150.00	\$ 150.00	+
10	ROCKER PANEL SEALANT RH <i>NE</i>	1	\$ 150.00	\$ 150.00	+
11	FRONT WHEEL RIM RH <i>ut</i>	1	\$ 250.00	\$ 250.00	180.
12	FRONT WHEEL TYRE RH <i>NE</i>	1	\$ 480.00	\$ 480.00	+
13	SLIDING DOOR SEALANT RH <i>NE</i>	1	\$ 150.00	\$ 150.00	+
14	SLIDING DOOR INNER TRIM CLIP RH (SET) <i>NE</i>	1	\$ 60.00	\$ 60.00	30
15	REAR FENDER COWLING CLIP RH (SET) <i>NE</i>	1	\$ 50.00	\$ 50.00	+
16	REAR FENDER LOWER GUARD CLIP RH (SET) <i>NE</i>	1	\$ 60.00	\$ 60.00	10
17	REAR WHEEL RIM RH <i>NE</i>	1	\$ 250.00	\$ 250.00	+
18	REAR WHEEL TYRE RH <i>NE</i>	1	\$ 480.00	\$ 480.00	+
19	POWER STEERING OIL <i>NE</i>	1	\$ 180.00	\$ 180.00	+
20	BRAKE OIL <i>NE</i>	1	\$ 30.00	\$ 30.00	+

280

TOTAL \$ 2,900.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,200.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	1000
3	TUFF COAT	\$ 250.00	50
4	WIRING CHECK	\$ 180.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE & REFIX FRONT WINDSCREEN	\$ 120.00	X
7	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	✓
8	REMOVE AND REFIX DASH BOARD AND INTERNAL WIRING	\$ 850.00	X
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	220
10	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	X

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLT6737X**
MODEL : **TOYOTA SIENTA**
DATE OF ACCIDENT : 13.09.20
TIME OF ACCIDENT : 17:00HRS

11	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	X
12	FOUR WHEEL ALIGNMNET	\$ 120.00 80	X
13	TRANSFER REAR SLIDING DOOR MECHANISM	\$ 80.00	✓
14	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
15	RESET ABS LIGHT	\$ 350.00	X
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	X

TOTAL \$8,500.00

2400

TOTAL PARTS COST : \$ 23,616.24

TOTAL LABOUR COST : \$ 8,500.00

TOTAL REPAIR COST : \$ 32,116.24

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian Lj
1/S 16/09/20.

08 Days.

total: 9356.80
1/S: 7.41K