

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO.: 35766600C GST REG. NO.: 35766600C

28-10-20

Date Of Accident : 10-09-2020

OUR REF : SKA 4666S/T/20

SWAVE CAR RENTAL PTE LTD

1 Kaki Bukit Ave 6

#02-34 (Auto Bay)

Singapore 417883

TP ALG
LKK - Adrian Cecilia
Date Input: 16-09-20 to 19-09-20

ESTIMATE BILL ON VEH NO : SKA 4666S

MODEL : KIA CERATO

CHASSIS NO. : KNAFW411MA5252309

LIST ITEM

Rear Wheel Bearing Hup - RH

XLol N4

X 380.00

380.00

Less Discount 10%:

38.00

342.00

SPECIAL NETT ITEM

Rear Sport Rim - RH

Wt

400 ~~690.00~~

LABOUR CHARGE

To Remove & Refix Rear RH Wheel Bearing Hup.

X 120.00

To Remove & Refix Rear RH Sport Rim & Contact Wheel Balancing.

80 ~~120.00~~

To Respray Affected Areas.

400 ~~600.00~~

To Renew Damaged Parts, Straighten & Repair Rear RH Fender, Rear Bumper and Aligned All Parts.

200 ~~580.00~~

2,452.00

GST 7%:

171.64

TOTAL AMT:

2,623.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1080

L/S: 850 03 days.