

(08/11/13) we\$
ASS. REC. BY: Marcus

REF:

CC4/KC120009823/ues3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBP 6114H

at Workshop m/s

BHH

of

Insured:

SHA 4619P

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£8500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

13.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

17A 2169

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBP 6114H

Yr Regn:

519

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha NMAX 155

c.c

155

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

26956

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH3SG 431 000011169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or *affected*

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110-70-13

R:

130-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / *PIR* / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/7/20

D.O.I.

14/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/10/20 continued final fig & 957.00 with Raymond.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MS FIRST CAPITAL INSURANCE LTD

NO. : 36739

DATE : 10/09/2020
CLAIM NO. : 11610
POLICY NO. : MC/00792689

FROM : HASRIANAH

VEHICLE NO. : FBP6114H
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$50.00	50.00
2	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$10.00	10.00
3	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$27.00	27.00
4	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	1.00	\$12.00	12.00
5	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00	7.00
6	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00	7.00
7	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00	12.00
8	COVER LOWER RH (GREY) P/N: 63490	REPLACE	1.00	\$28.00	28.00
9	COVER SIDE LH (MATTE BLACK) P/N: 66090	REPLACE	1.00	\$37.00	37.00
10	COVER SIDE REAR LH (GREY) P/N: 63497	REPLACE	1.00	\$38.00	38.00
11	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	1.00	\$10.00	10.00
12	FOOTREST REAR LH P/N: 64241	REPLACE	1.00	\$16.00	16.00
13	FORK FRONT LH ASSY	REPLACE	1.00	\$350.00	350.00

*36739 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. : 2002-1-0383
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	4.00	\$63.00	220 252.00
15	LAMP SIGNAL FRONT LH P/N: 59587	REPLACE	1.00	\$34.00	one 34.00
16	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	one 35.00
17	MUDGUARD FRONT (GREY) P/N: 63496	REPLACE	1.00	\$49.00	one 49.00
18	PANEL 1 (GREY) LH P/N: 59584	REPLACE	1.00	\$21.00	one 21.00
19	RIVET P/N: 56583	REPLACE	10.00	\$2.00	see 20.00
20	STAND MAIN P/N: 58138	REPLACE	1.00	\$63.00	see 63.00
21	STICKER (MCDONALD)COVER SIDE P/N: 60256	REPLACE	1.00	\$17.00	see 17.00
22	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	35 56.00

SUB TOTAL

\$1,151.00

GST @ 7 %

\$80.57

GRAND TOTAL (SGD)

\$1,231.57

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

780

10

P-702

L-255

957

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*36739 *

bSAFE3



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-14033
ISO 9001:2015



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

NO. : 36739

- Rev. 1

DATE : 10/09/2020
CLAIM NO. : 11610
POLICY NO. : MC/00792689

FROM : HASRIANAH

VEHICLE NO. : FBP6114H
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$50.00 Disc %: 10.00	45.00
2	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$10.00 Disc %: 10.00	9.00
3	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$27.00 Disc %: 10.00	24.30
4	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
5	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
6	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
7	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
8	COVER LOWER RH (GREY) P/N: 63490	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
9	COVER SIDE LH (MATTE BLACK) P/N: 66090	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
10	COVER SIDE REAR LH (GREY) P/N: 63497	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
11	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	1.00	\$10.00 Disc %: 10.00	9.00
12	FOOTREST REAR LH P/N: 64241	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
13	FORK FRONT LH ASSY	REPLACE	1.00	\$350.00 Disc %: 10.00	315.00

*36739 *

*bizSAFE*₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$220.00	220.00
15	LAMP SIGNAL FRONT LH P/N: 59587	REPLACE	1.00	\$34.00	30.60
16	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	31.50
17	MUDGUARD FRONT (GREY) P/N: 63496	REPLACE	1.00	\$49.00	44.10
18	PANEL 1 (GREY) LH P/N: 59584	REPLACE	1.00	\$21.00	18.90
19	RIVET P/N: 56583	REPLACE	10.00	\$2.00	18.00
20	STICKER (MCDONALD)COVER SIDE P/N: 60256	REPLACE	1.00	\$17.00	15.30
21	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$35.00	35.00

SUB TOTAL

\$957.00

GST @ 7 %

\$66.99

GRAND TOTAL (SGD)

\$1,023.99

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*36739 *

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

bizSAFE₃
 CERT NO. 2002-14083
 ISO 9001 2015