



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 36739

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MS FIRST CAPITAL INSURANCE LTD

DATE : 10/09/2020
CLAIM NO. : 11610
POLICY NO. : MC/00792689

FROM : HASRIANAH

VEHICLE NO. : FBP6114H
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$50.00	50.00
2	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$10.00	10.00
3	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$27.00	27.00
4	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	1.00	\$12.00	12.00
5	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00	7.00
6	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00	7.00
7	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00	12.00
8	COVER LOWER RH (GREY) P/N: 63490	REPLACE	1.00	\$28.00	28.00
9	COVER SIDE LH (MATTE BLACK) P/N: 66090	REPLACE	1.00	\$37.00	37.00
10	COVER SIDE REAR LH (GREY) P/N: 63497	REPLACE	1.00	\$38.00	38.00
11	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	1.00	\$10.00	10.00
12	FOOTREST REAR LH P/N: 64241	REPLACE	1.00	\$16.00	16.00
13	FORK FRONT LH ASSY	REPLACE	1.00	\$350.00	350.00

*36739 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. : 2002-1-0383
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	4.00	\$63.00	220 252.00
15	LAMP SIGNAL FRONT LH P/N: 59587	REPLACE	1.00	\$34.00	one 34.00
16	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	one 35.00
17	MUDGUARD FRONT (GREY) P/N: 63496	REPLACE	1.00	\$49.00	one 49.00
18	PANEL 1 (GREY) LH P/N: 59584	REPLACE	1.00	\$21.00	one 21.00
19	RIVET P/N: 56583	REPLACE	10.00	\$2.00	per 20.00
20	STAND MAIN P/N: 58138	REPLACE	1.00	\$63.00	one 63.00 X
21	STICKER (MCDONALD)COVER SIDE P/N: 60256	REPLACE	1.00	\$17.00	per 17.00
22	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	35 56.00

SUB TOTAL
GST @ 7 %

\$1,151.00
\$80.57

GRAND TOTAL (SGD)

\$1,231.57

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*36739 *

bizSAFE₃



CERT NO. 2002-142063
ISO 9001:2015

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759