



08 OCT 2020

Your Ref : D20002945MFSH
Our Ref : TP/11610/FBP6114H/SHA4619P

BY EMAIL & HAND

MS First Capital Insurance Ltd
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

Dear Sir / Madam,

Accident Involving FBP6114H & SHA4619P on 23/07/2020

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$1,023.99
2. Loss of Use (3 days x \$20)	\$ 60.00
3. LTA Vehicle Insurance Search Fee	\$ 7.45
TOTAL	<u>\$1,091.44</u>

We attached our Letter of Demand, Tax Invoice and LTA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

.....
Raymond Tan
Manager/Insurance Dept
Tel : 6281 6520 ext. 220
Fax : 6284 2969
Email : raymond@bhh.com.sg





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877


MOTOR CLAIMS DEPT

Invoice No. : **LECR20038543-I11610**
Invoice Date : 07/10/2020
Payment Due Date : 06/11/2020

CLAIM NO. : 11610
POLICY NO. : MC/00792689
VEHICLE NO. : FBP6114H
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)


S/N	Description	Action	Qty	Unit Price	Amount
1	BOARD FOOTREST LH	REPLACE	1	\$50.00	\$45.00
				Disc %: 10%	
2	BOX FILTER AIR OUTER FRONT	REPLACE	1	\$10.00	\$9.00
				Disc %: 10%	
3	COVER CLUTCH OUTER	REPLACE	1	\$27.00	\$24.30
				Disc %: 10%	
4	COVER CLUTCH OUTER DAMPER 1	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
5	COVER CLUTCH OUTER DAMPER 2	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
6	COVER CLUTCH OUTER DAMPER 3	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
7	COVER CLUTCH OUTER DAMPER 4	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
8	COVER LOWER RH (GREY)	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
9	COVER SIDE LH (MATTE BLACK)	REPLACE	1	\$37.00	\$33.30
				Disc %: 10%	
10	COVER SIDE REAR LH (GREY)	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
11	FOOTREST REAR LH	REPLACE	1	\$16.00	\$14.40
				Disc %: 10%	
12	FORK FRONT LH ASSY	REPLACE	1	\$350.00	\$315.00
				Disc %: 10%	
13	LAMP SIGNAL FRONT LH	REPLACE	1	\$34.00	\$30.60
				Disc %: 10%	
14	MIRROR LH	REPLACE	1	\$35.00	\$31.50
				Disc %: 10%	
15	MUDGUARD FRONT (GREY)	REPLACE	1	\$49.00	\$44.10
				Disc %: 10%	
16	RIVET	REPLACE	10	\$2.00	\$18.00
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
17	STICKER (MCDONALD)COVER SIDE	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
18	EMBLEM (YAMAHA) LOGO	REPLACE	1	\$10.00	\$9.00
				Disc %: 10%	
19	PANEL 1 (GREY) LH	REPLACE	1	\$21.00	\$18.90
				Disc %: 10%	
20	LABOUR	Supply/Install	1	\$220.00	\$220.00
21	TRANSPORT CHARGES		1	\$35.00	\$35.00
SUB TOTAL					\$957.00
GST @ 7 %					\$66.99
GRAND TOTAL (SGD)					\$1,023.99

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



Printed by : RAYMOND

bizSAFE₃

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 11 Sep 2020 / 10:30:22

Receipt Date/Time : 11 Sep 2020 / 10:30:10

Tax Invoice/Receipt

Receipt No. : ITNET-00000-200911-000916

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHA4619P				
As at 23 Jul 2020/17:30:00				
Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED				
1	Insurance Enquiry - SHA4619P Enquiry Fee 20200911102816304383	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	k2egzkr0-- 7L499320X11466722	Credit Card		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.