



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104502

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 28/06/2021
Reference CC4/FCI20009829/R1es3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBH 5884S
Insured Veh. SHA 9485A
Claim No. D20003674MFSH
Policy No. D-20094921MFSH
Accident Date 10/09/2020
Inspection Date 14/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20009829/R1es3q2	
			Date: 28/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9485A	Veh. Inspected	GBH 5884S
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D20003674MFSH	Excess (\$)	0.00
	Assign From	ERIC	Assign Date	14/09/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE VAN TURBO 5DR	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFHT02P100243960	Colour	WHITE
	Odometer	66849 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	NEXEN	6 mm
	L/H Front Tyre	195 R15C	NEXEN	6 mm
	R/H Rear Tyre	195 R15C	NEXEN	6 mm
	L/H Rear Tyre	195 R15C	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/09/2020	Inspection Date	14/09/2020
	Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5884S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	TORN	578.00	578.00
1	FRT BUMPER RETAINER RH	CUT	271.75	271.75
1	FRT BUMPER SIDE COVER RH	MISSING	61.10	61.10
1	FRT BUMPER TOW COVER	MISSING	53.10	53.10
1	FRT BUMPER REINFORCEMENT	BENT	571.75	571.75
1	FRT BUMPER LOWER GRILLE	CUT	274.45	274.45
10	FRT BUMPER CLIP @\$12.90	NECESSARY	129.00	129.00
1	FRT GRILLE TOP	SCRATCHED	371.40	371.40
1	FRT GRILLE LOW	SCRATCHED	571.75	571.75
1	FRT GRILLE BASE	SERVICEABLE	581.90	-
1	FRT BRACE PANEL	BENT	175.45	175.45
1	FRT BONNET	TO REPAIR SEE LABOUR	781.10	-
2	FRT BONNET HINGE @\$121.10	SERVICEABLE	242.20	-
1	AIR CLEANER BOX	CRACKED	972.45	972.45
1	FRT STEP GARNISH LOWER RH	SERVICEABLE	231.35	-
1	FRT HEADLAMP RH	SCRATCHED	781.90	781.90
1	FRT TOYOTA LOGO	NECESSARY	121.10	121.10
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	974.41	-
1	TOP BEAM	SERVICEABLE	371.75	-
1	TOP BEAM BRACKET RH	SERVICEABLE	289.90	-
1	AIRCON CONDENSER	BENT	1,717.45	1,717.45
1	AIRCON CONDENSER BRACKET RH	SERVICEABLE	274.45	-
1	FRT BUMPER TOW COVER (ADDITIONAL)	MISSING	53.10	53.10
	LESS 25% DISCOUNT		-2,612.70	-1,675.94
			7,838.11	5,027.81
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NUMBER PLATE (SN)	BENT	35.00	35.00
			35.00	35.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK ,WELD ,REMOVE & REPLACE ABOVE PARTS .INCLUSIVE OF THE REPAIR OF FRT BONNET AND FRT SUPPORT PANEL .		800.00	600.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		850.00	600.00
	TO CHECK WIRING.		30.00	30.00
	TO TOP UP AIRCON GAS.		100.00	100.00
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	100.00	-
			1,880.00	1,330.00
GRAND TOTAL			9,753.11	6,392.81
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,100.00

Report Ref No. CC4/FCI20009829/R1es3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 5884S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 5884S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

