

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

AAD2009-052

*Not Authorised
Recovery B4 paint*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

11 SEP 2020

SHD 9231A
JTDKB3FU403083400
TOYOTA
PRIUS
10.9.2020
FCIL
30/08/2019

	PART		LIST		
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	<i>Ry</i> 1,300.70	✓	
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	<i>R</i> 97.50	} X	
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	<i>R</i> 110.60		
1	CHECK ASSY, FRONT DOOR	\$	<i>SL</i> 183.80		
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	<i>SL</i> 390.60		
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	<i>SL</i> 193.50		
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRONT RH	\$	<i>SL</i> 926.00		
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	<i>SL</i> 238.30	} X	
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	<i>Me</i> 13.30		✓
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	<i>Me</i> 43.50		✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	<i>Me</i> 26.30	✓	
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	<i>R</i> 603.20	X	
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	<i>Ry</i> 1,294.90	✓	
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	<i>Me</i> 21.90	✓	
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	<i>Me</i> 34.90	✓	
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	<i>Me</i> 15.40	✓	
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	<i>R</i> 87.10	X	
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	<i>SL</i> 926.00	X	
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	<i>SL</i> 206.70	X	
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>SL</i> 594.80	X	
1	FENDER SUB-ASSY, FRONT RH	\$	<i>Ry</i> 977.80	✓	
1	LINER, FRONT FENDER, RH	\$	<i>SL</i> 206.70	X	
1	EMBLEM, SIDE PANEL	\$	<i>Me</i> 54.60	✓	
1	PROTECTOR, FRONT FENDER SIDE PANEL, RH	\$	<i>SL</i> 93.90	X	
1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>SL</i> 100.40	X	
1	COVER, FRONT BUMPER	\$	<i>SL</i> 516.00	X	
1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>R</i> 871.50	X	
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>SL</i> 139.80	X	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

TOTAL	\$	10,269.70
25%	\$	2,567.43
	\$	7,702.28

Special Nett				
1	FRONT DOOR STICKER 'TRANS-CAB'	\$	<i>nn</i> 100.00	<i>60sn</i>
1	REAR DOOR STICKER "6555-3333"	\$	<i>nn</i> 100.00	<i>60sn</i>
1	FRONT WHEEL RIM COVER	\$	<i>sn</i> 211.50	} <i>X</i>
1	REAR WHEEL RIM COVER	\$	<i>sn</i> 211.50	
2	WINDSCREEN SEALANT	\$	<i>nn</i> 150.00	
1	WINDSCREEN MOULDING	\$	<i>nn</i> 200.00	
1	WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 130.00	
1SET	FRONT FENDER LINER CLIP	\$	<i>nn</i> 70.00	
1SET	ROCKER PANEL MOULDING CLIP	\$	<i>nn</i> 60.00	
1	FRONT BUMPER CLIP	\$	<i>nn</i> 80.00	
1SET	BUMPER RETAINER CLIP	\$	<i>nn</i> 70.00	
1	REAR FENDER LINER CLIP	\$	<i>nn</i> 70.00	
1	REAR BUMPER CLIP	\$	<i>nn</i> 80.00	
TOTAL		\$	1,533.00	

TOTAL PARTS	\$	9,235.28
--------------------	----	-----------------

LABOUR

To transfer of front door fittings, attachment and perform water seepage test.	\$	170.00	<i>60l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>500l</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	170.00	<i>60l</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	<i>90l</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>

AAD2009-052

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>889</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of windscreen glass to facilitate bodywork repair.	\$	170.00	X
To remove and refit fender fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 350.00	X
TOTAL	\$	5,250.00	

Over All Total \$ 14,485.28

(PART-BY-PART) Repair Days *20 days*
3 days

For Official Use

Prepared By : _____ (Accident Dept)	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p>
Verify By : _____ (Accident Workshop)	
Checked By : _____ (Finance Dept)	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2020 16:47
Date Of Accident	10/09/2020 11:45
Exact Location Of Accident	13 DEMPSEY HILL CARPARK DRIVEWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9231A
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P2348706
Cover Note Number	

Driver

Name of Driver	NG HIN WOO
NRIC No	SXXXX028I
Date Of Birth	08/01/1955
Occupation	OUTDOOR
Date Of Driving Pass	15/06/1977
Driving Experience	43 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91847118
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 111 BISHAN STREET 12
 #03-156
 Postcode 570111
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 10/09/2020 AT ABOUT 1145HRS, I WAS TRAVELLING STRAIGHT ALONG THE CARPARK DRIVEWAY OF 13, DEMPSEY HILL TOWARDS DEMPSEY ROAD. SUDDENLY I FELT AN IMPACT ON THE RIGHT SIDE OF MY TAXI. VEHICLE B(SHA1406G) HAS CAME OUT OF THE SIDE ROAD ON MY RIGHT WITHOUT CHECKING FOR ON-COMING VEHICLE AND COLLIDED ONTO MY TAXI'S RIGHT SIDE PORTION.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE SIZE TOO LARGE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA1406G
 Vehicle Make/Model/Colour COMFORT
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GEA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: